

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78977
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11703 - 2026 COUGAR 316RLS 4YDFCGR26T2504802

VIN: 4YDFCGR26T2504802 HIN:

SER#: 4YDFCGR26T2504802

Mileage: 0

Work Order Comp: 19 MAR 26

Auth. No:

Dealer #: 1194

Warr. Date:

Work Order Date: 05 FEB 26

Inv #: 427553

WO # Job # Description JOB INFORMATION

78977 1 THE LIGHT SWITCH FOR THE REFRIGERATOR DOOR IS BROKEN.
The light switch is broken through the housing on the top of the
fridge. Im not sure if we need just a switch or a new housing.
Broken Fridge switch to interior light.
Received part and pulled unit into Bay. Part was Grey in color
and parts in Fridge is Black... informed Pete and Ben, Ben said
to install Grey Iswitch anyways. Used my pick tool and needle
nose pleyer to dig broken switch and housing out of cutout and
installed new grey switch.
78977 2 THE SEAL ON THE FRONT COMPARTMENT DOOR IS BUNCHED UP.
The seal isn't laying down flush.
Secured seal to the door frame.
78977 3 THERE IS A BLACK MARK ON THE BATHROOM COUNTER
There's a black mark on the counter.
Removed with mineral spirits and a rag.
78977 4 THERE ARE SCRATCHES ON THE BEDROOM DRESSER.
Scratches on the top of the dresser top.
Removed scratches with mineral spirits.
78977 5 THE SCREEN DOOR LATCH NEEDS ADJUSTED
The screen door latch is to far away from the door and wont hold
it closed.
Installed 2 washers under the latch to move it towards the door.

Claim : 78977

 WO # Job # Description JOB INFORMATION

78977 6 THE MAIN DOOR IS REALLY HARD TO CLOSE
 The door is not shutting. The top and the bottom are hitting the
 frame.
 Placed a wooden block on the top and the bottom corner and forced
 the door shut. I the pushed around the door on the outside.
 Removed the block and now the door is shutting.

 Part No Job# Description PARTS Qty Price Total

 2021149676 1 Furrion Replacement RV Refrigerat 1.00 74.59 74.59

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISCELLANEOUS REPAIR 0.50 180.00 90.00
 Z990 1 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 2 MISCELLANEOUS REPAIR 0.20 180.00 36.00
 Z990 3 MISCELLANEOUS REPAIR 0.10 180.00 18.00
 Z990 4 MISCELLANEOUS REPAIR 0.20 180.00 36.00
 Z990 5 MISCELLANEOUS REPAIR 0.20 180.00 36.00
 Z990 6 MISCELLANEOUS REPAIR 0.20 180.00 36.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 FED-EX - HINGE KIT 1.00 8.44 8.44

Parts Total: 74.59
 Labour Total: 252.00
 Sublet Total: 0.00
 Extras Total: 8.44

>>>> Claim Total: 335.03

Customer Signature: _____

Date: _____