



Pre-Authorization

Pre-Authorization number	PREAUTH732 69 (PA03965516	Reference no.78977	Status	Approved
--------------------------	---------------------------------	--------------------	--------	----------

Servicing Dealer 1194	Name Basden's American RV	Address 600 E Baseline Rd Evansville, IN 47725	VIN 4YDFCGR26T2504802	Retail sold on
-----------------------	---------------------------	---	-----------------------	----------------

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.

Root		Approved Actual				Base		Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	hours	
4149006A	Refrigerator - 12 Volt	0	0.5	0.5		1	0.5	Complaint: THE LIGHT SWITCH FOR THE REFRIGERATOR DOOR IS BROKEN. Cause: The light switch is broken through the housing on the top of the fridge. Im not sure if we need just a switch or a new housing. Correction: REPLACE SWITCH AND HOUSING
2302437B	Compartment Door - Weather Seal	0	0.2	0.2		1	0.2	Complaint: THE SEAL ON THE FRONT COMPARTMENT DOOR IS BUNCHED UP. Cause: The seal isn't laying down flush. Correction: Secured seal to the door frame.
3101903A	Countertop - Bathroom - Repair	0	0.2	0.1		1	0.2	Complaint: THERE IS A BLACK MARK ON THE BATHROOM COUNTER Cause: There's a black mark on the counter. Correction: Removed with mineral spirits and a rag.
3301803A	Coffee Table - Repair	0	0.2	0.2		1	0.2	Complaint: THERE ARE SCRATCHES ON THE BEDROOM DRESSER. Cause: Scratches on the top of the dresser top. Correction: Removed scratches with mineral spirits.
2300102A	Entrance Door - Hinged - Repair	0	0.2	0.2		1	0.2	Complaint: THE SCREEN DOOR LATCH NEEDS ADJUSTED Cause: The screen door latch is to far away from the door and wont hold it closed. Correction: Installed 2 washers under the latch to move it towards the door.
2300103F	Entrance Door - Hinged - Adjust Door or Lock	0	0.3	0.2		1	0.2	Complaint: THE MAIN DOOR IS REALLY HARD TO CLOSE Cause: The door is not shutting. The top and the bottom are hitting the frame. Correction: Placed a wooden block on the top and the bottom corner and forced the door shut. I the pushed around the door on the outside. Removed the block and now the door is shutting.
Pre-Authorization number: PREAUTH73269				1.4				

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.