

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
<b>BASDEN RV CENTER INC</b>		<b>CLAIM</b>	2599578
<b>DBA AMERICAN RV CENTER</b>		<b>CLAIM ORIGIN</b>	WEB
<b>600 E BASELINE ROAD</b>		<b>ORIGINAL CLAIM ID</b>	
<b>EVANSVILLE, IN 47725</b>		<b>VIN</b>	5ZT2RMAC8TL019637
<b>USA</b>		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$185.00	<b>SITE/WAREHOUSE</b>	224 / 224
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	RMT12R
		<b>DEALER RO #</b>	79010
		<b>CLAIM START DATE</b>	03/04/2026
		<b>CLAIM END DATE</b>	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	40-106-24-11-001258	Heating Pad - Holding Tank - Electrical/12 Volt Exterior/Repair/Electrical		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2026-03-04 16:37:19 :: TANK HEATERS FALLING OFF Heating pad The heating pad on the fresh tank and grey tank wasnt sticking to the tanks. Applied 3m tape primer then pressed them against the tank and added tape for temporary hold.			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$37.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$37.00
	<b>Notes</b>			

### Labor

<b>Line# 2</b>	<b>Operation Code</b>	<b>Operational Description</b>			
	70-170-01-00-002042	Suburban Furnace Blower Wheel - Appliances/Furnace (Suburban)/Replace/No Tread Code			
	<b>Complaint, Cause, Correction</b>				
	Original Note : bhoffman@americanrvcenter.com, 2026-03-04 16:37:44 :: FURNACE FAN IS TICKING Fan blade During the pdi the turned on the furnace and the furnace fan was ticking. Shut off the lp then unscrewed the furnace cover. Disconnected thepower wiresfrom the furnace. Disconnected the lp line. Unscrewed the furnace from the cabinet. Bench tested the furnace and found thebig fan blade was running the metal frame. Disassembled the furnace. Unscrewed the fan blade from the motor. Shaved the fan blade at the ends where it was rubbing. Screwed on the fan to the motor and assembled the furnace. Tested the furnace by bench testing. Furnace was quiet after, rotated the furnace to make sure it was solid and quiet. Put the furnace back inside the camper. Connected the lp line and wires. Mounted the furnace to the cabinet and screwed on the cover. Tested the furnace again inside the camper and it still was quiet. Took pictures of the process.				
<b>Model#</b>	na	<b>Dlr Sub Hrs</b>	1.40	<b>Sub Labor Amt</b>	\$259.00
<b>Serial#</b>	na	<b>Appr Hrs</b>	1.25	<b>Appr Labor Amt</b>	\$231.25
	<b>Notes</b>				
	3/5- Sent to vendor for consideration VCB Suburban will authorize the repair of the Motor, warranty allowance time is 1.25 hrs. Samantha Hartley Tech Service Rep I Suburban, An Airxcel Brand 676 Broadway St. Dayton, TN 37321 574-247-9235 www.Airxcel.com				

### Labor

<b>Line# 3</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	50-134-01-00-003673	Rubber LP Supply Line - LP Gas/LP Gas System/Replace/No Tread Code		

