



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79021
Promised Date:
08 FEB 26



Customer #: 56517
MCALLISTER, ERIC G.



CUSTOMER WORK ORDER

WO #: 79021

Customer: 56517 - MCALLISTER, ERIC
G. - 812-306-7047

Tag:

Author: BH

Location: DELIVERY 0226

Stock #: 11712

Stock Desc: 2026 TT COACHMEN

CATALINA SUMMIT 164BHX

Chassis #: 5ZT2CAEC4TK014306

Serial #: 5ZT2CAEC4TK014306

Mileage: 0

Licence:

Invoice #:

Date In: 12 FEB 26

Promised: 28 FEB 26

Date Sched:

Completed: 28 FEB 26

Warr. Date: 26 FEB 26

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER CATALINA TK014306

CAUSE: Pdi

CORRECTION: Pull the camper in from the front lot into the service bay. Got a new battery box , but not a lid and filled one twenty pound lp tank. Mounted the battery box and drilled holes for drainage. Put a used battery in the battery box. Tested the running, lights brakes and breakaway switch. Filled the fresh tank.Plug in the shore powered from the camper. Check and set the tire pressure to sixty five psi. Check and set the lug nuts to 110ftlbs. Extended the stability jacks. Inspected the roof membrane and sealer, no touch-up needed at this time. Went inside the camper and opened the awning and closed the awning then checked the awning lights. Went through and checked the 120v gfci outlets, tv, ac, microwave, converter output. Tested the smoke alarm and lp detector. Moved the mattress to get to the water heater. Checked the 12volt items such as usb ports, converter output, lights. Checked the cabinet doors and the cabinet next to the microwave has a blemish. Tested the windows and blinds, for a loose screw on the big window. Tightened the screw. Unscrewed the burner off the stove and lp line then connected the manometer to the lp line. Turned on the water pump to dewinterize the camper. Connected the garden hose to the city water connection and ran the water heater and furnace for the lp drop test. Adjusted the lp regulator as necessary. Retracted the stability jacks. Disconnected the manometer from the stove and put the cover back on the stove. Removed the plastic film from appliances. Disconnected the test battery and gave camper to wash bay. Missing a lid for the battery box.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED



NUMBER OF GALLONS USED _____

CAUSE: Winterizing 2 gallons

CORRECTION: Connected the sewer hose and drained the black and grey tanks. Drained the fresh tank. Turned the valves at the water pump then added 2 gallons through the kitchen faucet, shower and toilet. Depressed city water connection and water heater.

Labor Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	SAR	N/C

Parts Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: CABINET DOOR PEELING NEXT TO THE MICROWAVE

CAUSE: Cabinet door

CORRECTION: Took pictures of the peeling cabinet door. Put in a parts request for a new cabinet door.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	18.50
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	18.50

Parts Part #	Description	Qty	Price	Total
F100417103	DOOR, CABINET FPS 15.75W X 12.75H M&	1.00	18.21	18.21

Other Services Code	Description	Qty	Price	Total
FRT	UPS-CABINET DOOR	1.00	16.30	16.30

Subtotal for Job #1: 108.51

Job #2 - Warranty

COMPLAINT: SEALER ON WINDOWS

CAUSE: Sealer on windows

CORRECTION: Took pictures the used mineral spirits to clean off the sealer

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	37.00

Subtotal for Job #2: 37.00

Job #3 - Warranty

COMPLAINT: BUBBLES IN DECALS

CAUSE: Bubbles

CORRECTION: Took pictures then used a heat gun to help massage the bubbles out of the decals.

Labor Code	Description	Mechanic	Total
------------	-------------	----------	-------



Z990

MISC LABOUR CODE (EXTERNAL)

SAR

37.00

Subtotal for Job #3:

37.00

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery. Exterior inspection looks good. Roof inspection looks good. Interior inspection hooked up to city water and flushed out all the lines. Stove works properly microwave works properly refrigerator works properly ac works properly furnace works properly water heater works properly tv antenna works properly and tv and radio. Tv radio and Awning lights remotes are in cabinet above sink. Lp drop test on stove with furnace and water heater running made no adjustments to regulator system works properly. Put water in fresh tank and flushed out all the lines. Water pump works properly drained black tank and gray tank and fresh tank.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT:

0.00

Job #WINTER* - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Turned valve to winterize and pumped winterize solution through the water pump to bathroom shower hot and cold until solution was there then repeated for toilet and kitchen faucet. Drained water heater and depressed city water inlet. Drained black tank and gray tank and fresh tank. Used 2 gallons of winterize solution.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JTW	N/C
Z990	WINTERIZE UNIT	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER*:

0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

W/O: 79021
Promised Date: 28 FEB 26Customer #: 56517
MCALLISTER, ERIC G.



Parts				
Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Job #4 - Internal

COMPLAINT: BALL BAR PIN CLIP

CAUSE: Install hitch and sway control

CORRECTION: Set the hight on the hitch. Secured the hitch and the sway bar to the truck. Installed d rings on the chain holders.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts				
Part #	Description	Qty	Price	Total
CUR40067	PACKAGED HITCH BALL 7.5K 2 5/16IN X	1.00	N/C	N/C
21581	5/8IN HITCH PIN SUPER DUTY PKG	1.00	N/C	N/C
V7001	ADJUSTABLE BALL MOUNT 4 POSITION 6K	1.00	N/C	N/C
Subtotal for Job #4:				0.00

Job #SWAY - Internal

COMPLAINT: SWAY CONTROL INSTALLED ON ALL OTHERS

CAUSE: Install sway control

CORRECTION: Measured and drilled and mounted the ball plates on unit. And toqured the ball to spec. And put it in side compartment

Labor			
Code	Description	Mechanic	Total
SWAY	SWAY CONTROL INSTALLED	JTW	N/C
SWAY	SWAY CONTROL INSTALLED	JTW	N/C

Parts				
Part #	Description	Qty	Price	Total
BRV17200	DELUXE SWAY CONTROL	1.00	N/C	N/C
DRT26003	CLSIII SWAY CONT ADAPTER	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #SWAY:				0.00

Job #BCWT - Internal

COMPLAINT: INSTALL DIGITAL, PROPORTIONAL BRAKE CONTROL IN TRUCK/SUV

CAUSE: The truck needs a trailer brake controller installed

CORRECTION: I installed a new trailer brake controller in the truck. I used an OEM type harness and checked the 7-way output. Everything is working as it should.

Labor			
Code	Description	Mechanic	Total
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C

Parts				
Part #	Description	Qty	Price	Total
14636	7WAY PLASTIC CAR END	1.00	N/C	N/C



19-0938	9 WAY CONNECTOR - BRACKET	1.00	N/C	N/C
19-1441	16-3030 30A CIRCUIT BREAKER	1.00	N/C	N/C
14-1015	8508220 PROPORTIONAL BRAKE CONTROL	1.00	N/C	N/C
81794	303600 2015-2025 FORD HARNESS	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #BCWT: 0.00

Parts Total: 18.21
Labour Total: 148.00
Sublet Total: 0.00
Extras Total: 16.30
WORK ORDER TOTAL: 182.51

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 03 Mar 2026

W/O: 79021
Promised Date: 28 FEB 26



Customer #: 56517
MCALLISTER, ERIC G.

