

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79026
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11714 - 2026 COUGAR SPORT 2700BH 4YDFCGN29T2504783
VIN: 4YDFCGN29T2504783 HIN: SER#: 4YDFCGN29T2504783
Mileage: 0 Work Order Comp: 23 FEB 26
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 13 FEB 26 Inv #: 426731

WO # Job # Description JOB INFORMATION

79026 4 WINDDOW IN DINETTE IS BROKEN AND BENT
Trim ring
Noticed the dinette window trim ring had been bent and handle had fallen off track. Pictures taken parts request submitted. Brought unit in. Connected battery to battery box. Grabbed lift so someone could hold window as I removed window ring. Went inside turned light on and removed bothnsides of valance at bottom bracket screw and at top where it connects to top piece. Removed top valance at two screws on both sides of it. Removed blinds three screws. Once all was removed and moved that sat infront of window ring pulled each screw out of window ring to remove it. Placed flat straight edge inside to measure wall thickness. Was is 1.75in thick. Placed window ring back together. Placed blinds back in place. Placed top valance back in place. Placed side valances back in place. Pictures taken. Wall measured. Recieved new trim ring. Placedbattery in battery box. Removed blinds and valance from window. Removed trim ring. Placed new ring in place. Placed valance and blinds back in place. Placed dinette baxk in place.

79026 1 BLIND STRING MOUNT NOT HOLDING IN WALL
Window shade screw pulled from wall
Shot the screw and adjusted the strings so blind works properly now

79026 2 BUNK SLIDING DOOR NOT ALIGNED

Claim : 79026

 WO # Job # Description JOB INFORMATION

 Sliding door out of adjustment
 Took trim board off and adjusted the hanger on the door to adjust
 the door with the frame. Door is adjusted and shuts properly now

79026 3 TRIM IN MASTER BED ISNT ATTACHED
 Loose trim
 Noticed loose trim in cabinets of master bedroom. Grabbed staple
 gun an stapled trim into place to secure. Pictures taken.

 Part No Job# Description PARTS Qty Price Total

 680352 4 WINDOW TRIM RING 1-3/4" WALL THIC 1.00 20.09 20.09

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 4 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 4 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 4 MISCELLANEOUS REPAIR 0.25 180.00 45.00
 Z990 4 MISCELLANEOUS REPAIR 0.75 180.00 135.00
 Z990 1 MISCELLANEOUS REPAIR 0.10 180.00 18.00
 Z990 2 MISCELLANEOUS REPAIR 0.20 180.00 36.00
 Z990 3 MISCELLANEOUS REPAIR 0.10 180.00 18.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 4 UPS-WINDOW TRIM RING 1.00 37.74 37.74

Parts Total: 20.09
 Labour Total: 252.00
 Sublet Total: 0.00
 Extras Total: 37.74

>>>> Claim Total: 309.83

Customer Signature: _____

Date: _____