



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79026
Promised Date:
26 FEB 26



CUSTOMER WORK ORDER

WO #: 79026

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0302 CHECK STATUS WITH
CCV

Stock #: 11714

Stock Desc: 2026 5W KEYSTONE

COUGAR SPORT 2700BH

Chassis #: 4YDFCGN29T2504783

Serial #: 4YDFCGN29T2504783

Mileage: 0

Licence:

Invoice #:

Date In: 13 FEB 26

Promised: 28 FEB 26

Date Sched:

Completed: 23 FEB 26

Warr. Date:

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CAUSE: Pdi

CORRECTION: Pulled the camper into the service bay. Disconnected the lp tanks then filled 2 30lb lp tanks. Opened the front compartment and put in a used battery. Plugged in the test box for the brakes, 4 way flat at rear bumper, breakaway switch and running lights. Checked and set the lug nuts to 110ftlbs. Checked and set the tires to 80PSI. Went on the roof membrane and sealer, no touch-up needed at this time. Plugged in the factory shore cord to a 50 amp service. Connected the garden hose to the city water connection to fill the fresh tank then turned the valve to flow in city. Opened the entry door and compartment doors. Pushed the button for auto level and it leveled. Adjusted the entry steps. Opened the windows and blinds, emergency exits. Found the window in the dinette is broken and bent. Found the blind string in the bunk wasn't attached. Tested the smoke alarm and lp detector. Turned on all the lights, range hood, fridge, test the usb ports and 120v gfci outlets, microwave, both ACs, set tv and test tv to local channels. Opened the ceiling vent and fans then closed. Connected the manometer to the quick connection to start the lp drop test. Tested the stove and oven. Opened the kitchen faucet to let the water heater run and the furnace. Adjusted the lp regulator as necessary during the lp drop test. Let the tanks fill up one at a time to verify they were correct. Opened and closed the cabinet doors, drawers and sliding doors. Found loose trim on both sides of the materbed. Checked each faucet for hot water. Retracted the leveling jacks. Disconnected the test battery.

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	SAR	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	SAR	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Customer #: 1000
BASDEN'S AMERICAN RV,





CAUSE: Winterizing 2 gallons

CORRECTION: Connected the sewer hose then drained the black and grey tanks. Drained the fresh tank. Turned the valve to winterization and connected a hose. Added 2 gallons through the kitchen faucet, bathroom faucet, low points, toilet, shower and spray port. Depressed city water connection and the water heater.

Labor			Mechanic	Total
Code	Description		SAR	N/C
Z990	WINTERIZE UNIT			
Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #1 - Warranty

COMPLAINT: BLIND STRING MOUNT NOT HOLDING IN WALL

CAUSE: Window shade screw pulled from wall

CORRECTION: Shot the screw and adjusted the strings so blind works properly now

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	18.00
Subtotal for Job #1:			18.00

Job #2 - Warranty

COMPLAINT: BUNK SLIDING DOOR NOT ALIGNED

CAUSE: Sliding door out of adjustment

CORRECTION: Took trim board off and adjusted the hanger on the door to adjust the door with the frame. Door is adjusted and shuts properly now

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	36.00
Subtotal for Job #2:			36.00

Job #3 - Warranty

COMPLAINT: TRIM IN MASTER BED ISNT ATTACHED

CAUSE: Loose trim

CORRECTION: Noticed loose trim in cabinets of master bedroom. Grabbed staple gun an stapled trim into place to secure. Pictures taken.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	18.00
Subtotal for Job #3:			18.00

Job #4 - Warranty

COMPLAINT: WINDDOW IN DINETTE IS BROKEN AND BENT

CAUSE: Trim ring





CORRECTION: Noticed the dinette window trim ring had been bent and handle had fallen off track. Pictures taken parts request submitted. Brought unit in. Connected battery to battery box. Grabbed lift so someone could hold window as I removed window ring. Went inside turned light on and removed bothnsides of valance at bottom bracket screw and at top where it connects to top piece. Removed top valance at two screws on both sides of it. Removed blinds three screws. Once all was removed and moved that sat infront of window ring pulled each screw out of window ring to remove it. Placed flat straight edge inside to measure wall thickness. Was is 1.75in thick. Placed window ring back together. Placed blinds back in place. Placed top valance back in place. Placed side valances back in place. Pictures taken. Wall measured. Recieved new trim ring. Placedbattery in battery box. Removed blinds and valance from window. Removed trim ring. Placed new ring in place. Placed valance and blinds back in place. Placed dinette baxk in place.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	0.00
Z990	MISCELLANEOUS REPAIR	CCV	0.00
Z990	MISCELLANEOUS REPAIR	CCV	45.00
Z990	MISCELLANEOUS REPAIR	CCV	135.00

Parts Part #	Description	Qty	Price	Total
680352	WINDOW TRIM RING 1-3/4" WALL THICKNE	1.00	20.09	20.09

Other Services Code	Description	Qty	Price	Total
FRT	UPS-WINDOW TRIM RING	1.00	37.74	37.74

Subtotal for Job #4: 237.83

Parts Total: 20.09
 Labour Total: 252.00
 Sublet Total: 0.00
 Extras Total: 37.74
WORK ORDER TOTAL: 309.83

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 23 Feb 2026

Customer Signature : _____

