

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2597427
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKB21TK096299
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT26DBH-94
		DEALER RO #	79032
		CLAIM START DATE	03/03/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 60-141-01-00-001577	Operational Description Tub Faucet with Shower Diverter - Plumbing/Shower, Tub Surround/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-03-03 12:35:56 :: THE SHOWER KNOB IS CRACKED ON THE COLD SIDE CrackedmCap on Bathtub Faucet handle. Found cracked cap on cold side of bathroom tube handle. Spoke to Ben and approvedmto replace faucet.	
Model#	Dlr Sub Hrs 0.40	Sub Labor Amt \$74.00
Serial#	Appr Hrs 0.50	Appr Labor Amt \$92.50
	Notes please change to the correct code DONE` changed to correct code	

Labor

Line# 2	Operation Code 30-307-01-00-000920	Operational Description Fireplace Remote Control - Interior/Fireplace/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-03-03 12:36:24 :: FIRE PLACE REMOTE DOES NOT WORK REPLACE WITH NEW	
Model#	Dlr Sub Hrs 0.00	Sub Labor Amt \$0.00
Serial#	Appr Hrs 0.00	Appr Labor Amt \$0.00
	Notes	

Submitted	Labor Amt	\$74.00	Approved	Labor Amt	\$92.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$74.00		Total	\$92.50

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.