

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

CLAIM STATUS Authorized
CLAIM 2589024
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2CAXB4TX036877
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 205 / 205
ITEM # ACAT323BHDSCKLE
DEALER RO # 79033
CLAIM START DATE 02/23/2026
CLAIM END DATE 01/01/1900

Labor rate: \$185.00

OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
30-102-12-00-001096 Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/
Resecure or Tighten/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-02-23 15:37:10 :: BATTEN STRIP IS LOOSE IN FRONT
COMPARTMENT The batten strip came loose. Secured batten with brad nails.

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50

Notes

Labor

Line# 2 Operation Code Operational Description
30-102-12-00-001096 Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/
Resecure or Tighten/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-02-23 15:37:43 :: BATTEN STRIP IS LOOSE IN REAR
COMPARTMENT Batten strip came loose. Secured batten strip with brad nails.

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50

Notes

Labor

Line# 3 Operation Code Operational Description
20-66-02-00-000678 Screen Door - Exterior/Entry Doors/Adjust/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-02-23 15:38:09 :: FRONT SCREEN DOOR IS HITTING
LATCH The screen door is hitting the latch for the screen door. Moved the latch over with a hammer. The door
now clears the latch.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00

Notes

Labor

Line# 4 Operation Code Operational Description
20-66-02-00-000678 Screen Door - Exterior/Entry Doors/Adjust/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-02-23 15:38:36 :: REAR SCREEN DOOR IS HITTING
LATCH The screen door is hitting the entry door latch. Moved the latch over with a hammer. The door now
clears the latch.

Model#	Dir Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
Notes				

Submitted	Labor Amt	\$111.00	Approved	Labor Amt	\$111.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$111.00		Total	\$111.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.