



Pre-Authorization

Pre-Authorization number	PREAUTH76262 (PA03968393)	Reference no.79036	Status	Approved
--------------------------	------------------------------	--------------------	--------	----------

Servicing Dealer 1194 Name Basden's American RV Address 600 E Baseline Rd VIN 4YDTSGG10SW104242 Retail sold on 2/16/2026
Evansville, IN 47725

Root		Approved		Actual	Base		Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	
5101906B	Light, Clearance & Taillight - Replace	0	0.2	0.2		1	Complaint: MARKER LIGHT NOT WORKING Cause: Front running light doesn't work Correction: Took light off made sure there was a good connection it was. Tested the light after i cut the wires and it doesn't work. So i put a parts request in for a new one that we didn't have. So i went and took one off a lot unit and took a picture of the donor unit vin and marked it with blue tape to replace it when it comes in. And wired the light up on sold unit and it works properly. And then i sealed it with clear silicone. Good to go KRV - Please retain part for possible return or additional photos. Keystone will notify you within 48 hours of submitting your claim for disposition of the part. Model+serial #s / vendor tags from complete component / vendor markings required
Pre-Authorization number: PREAUTH76262				0.2			

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.