



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 79059

### CUSTOMER WORK ORDER

WO #: 79059

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: BH  
Location: 0302 CHECK STATUS WITH  
CCV

Stock #: 11717  
Stock Desc: 2026 TT COACHMEN  
CATALINA SUMMIT 134RDX  
Chassis #: 5ZT2CABC2TK014342  
Serial #: 5ZT2CABC2TK014342  
Mileage: 0  
Licence:

Invoice #:  
Date In: 18 FEB 26  
Promised:  
Date Sched:  
Completed: 27 FEB 26  
Warr. Date:

#### Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER 2 HRS

CAUSE: New pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery box and filled 1 20# lp tank. Exterior inspection entry door striker has a loose stripped out screw. Other than the striker the exterior inspection looks good. Roof inspection looksgood. Awning fabric and hardware looks and works properly Awning lights work properly. Interior inspection hooked up to city water and flushed out all the lines. Stove works properly microwave works properly refrigerator works properly ac works properly furnace works properly water heater works properly all electrical outlets work properly and USB ports work properly all windows and blinds work properly tv antenna wont find any channels put a parts request in for new antenna. Water pump works properly

#### Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C

#### Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

**Subtotal for Job #PDINTT: 0.00**

#### Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*

UNITS WITH WASHING MACHINE OR ICEMAKER  
WILL BE EXTRA

\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*

NUMBER OF GALLONS USED \_\_\_\_\_

CAUSE: Winterize unit

CORRECTION: Turned valve to winterize and pumped winterize solution through the water pump to bathroom shower cold and hot until solution was there then repeated for toilet and kitchen faucet. Depressed city inlet port. Drained water heater turned water heater off Drained black tank and gray tank and fresh tank. Used 2 gallons of winterize solution



Customer #: 1000  
BASDEN'S AMERICAN RV,





Customer #: 1000  
BASDENS AMERICAN RV,



**Labor**

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JTW	N/C
Z990	WINTERIZE UNIT	JTW	N/C

**Parts**

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

**Subtotal for Job #WINTER: 0.00**

**Job #1 - Internal**

SCRW IN THE STRIKER IS STRIPPED AND FELL OUT

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: TV HAS NO ANTENNA

CAUSE: No signal from antenna  
Antenna not working.

CORRECTION: Took antenna off and checked the cable from booster to antenna it was good. So we hooked the cable back up and held antenna in you hand it worked but when i put antenna back on its base it didn't. So i took it back off and wiggled the wire that were coming out of the antenna itself it worked and then it wouldn't. So the wire connection in the antenna itself is were the issue is. I put a parts request in for a new antenna

Brought unit in. Antenna was not working on unit. Recieved new antenna. Removed screw holding top in and pulled off mount. Connect cable wires and am fm wire from old antenna and replaced with new one. Place antenna on mount locked in place and put screw in to hold. Went inside and turned on tv to test signal. Pictures and sound come through on antenna. New antenna works.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

**Parts**

Part #	Description	Qty	Price	Total
F100334599	ANTENNA, OMNI DIRECTIONAL	1.00	37.54	37.54

**Other Services**

Code	Description	Qty	Price	Total
FRT	UPS-ANTENNA	1.00	16.30	16.30

**Subtotal for Job #2: 146.34**

Parts Total: 37.54  
Labour Total: 92.50  
Sublet Total: 0.00  
Extras Total: 16.30  
**WORK ORDER TOTAL: 146.34**



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 27 Feb 2026

W/O: 79059

# Customer Work Order



Customer #: 1000  
BASDEN'S AMERICAN RV,

