

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2588514
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CABC4TK014343
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	203 / 203
OWNER INFORMATION		ITEM #	BCAT134RDX
		DEALER RO #	79061
		CLAIM START DATE	02/23/2026
		CLAIM END DATE	01/01/1900
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-44-19-00-004032	Roof Moldings - Side - Exterior/Roof/Reseal/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-02-23 12:24:19 :: DICOR ON ROOF IS GAPPING OPEN Void in the black dicor Cleaned area and put black dicor non sag in the void and touched both sides by light strip			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$37.00
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$37.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	20-66-02-00-000664	Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-02-23 12:24:58 :: ENTRY DOOR CATCHES ON STRIKER AND NOT CLOSING PROPERLY Entry door hard to open Had to adjust the screen door latch because it was dragging on the striker when opening the door and i adjusted the hings on the main entry door. Door works properly now			
	Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$55.50
	Serial#	Appr Hrs	0.30	Appr Labor Amt \$55.50
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	20-58-01-00-000608	Metal - Aluminum Siding, each sheet - Exterior/Metal, Aluminum Siding/Replace/ No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-02-23 12:25:35 :: OFF DOOR SIDE FRONT HAS DENT IN METAL Metal has a dent Noticed it on the exterior inspection NEED TO REPLACE THE MEATL			
	Model#	Dlr Sub Hrs	5.00	Sub Labor Amt \$925.00
	Serial#	Appr Hrs	5.00	Appr Labor Amt \$925.00
	Notes			
	AUTHORIZED AS REQUESTED			

Labor

Line# 4	Operation Code	Operational Description		
	40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-02-23 12:26:32 :: USB PORT DIRECTLY INSIDE ENTRY DOOR HAS NO POWER USB port no power Took usb port out of the wall and the wire were pulled out of the connector. So i put a new connector on it and the usb port works properly now			

Model#

Dir Sub Hrs 0.15

Sub Labor Amt \$27.75

Serial#

Appr Hrs 0.15

Appr Labor Amt \$27.75

Notes

AUTHORIZED AS REQUESTED

Submitted

Labor Amt	\$1,045.25
Parts & Freight	\$0.00
Total	\$1,045.25

Approved

Labor Amt	\$1,045.25
Parts & Freight	\$0.00
Total	\$1,045.25

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.