

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2598084
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CKFC3TY041823
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	095 / 095A
OWNER INFORMATION		ITEM #	CKT17JW-95
		DEALER RO #	79062
		CLAIM START DATE	03/03/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-95-24-00-000948	Dinette Table Top - Booth - Interior/Dinette/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-03-03 16:40:00 :: GLUE ON KITCHEN TABLE Glue on the table top. Removed glue with mineral spirits and a rag.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	20-69-24-00-000699	Compartment Door Frame - Exterior/Compartment Doors/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-03-03 16:50:33 :: OUTDOOR FRIDGE COMPARTMENT DOOR IS HITTING FRAME . The door is hitting the top of the frame. Took a block of wood and a hammer and pushed the frame up away from the door.			
	Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$18.50
	Serial#	Appr Hrs	0.10	Appr Labor Amt \$18.50
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	20-69-24-00-000699	Compartment Door Frame - Exterior/Compartment Doors/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-03-03 16:51:16 :: FRONT COMPARTMENT DOOR IS BENT The compartment door is bent outwards. Pushed back in with a hammer.			
	Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$18.50
	Serial#	Appr Hrs	0.10	Appr Labor Amt \$18.50
	Notes			

Labor

Line# 4	Operation Code	Operational Description		
	20-44-19-00-000553	Roof Moldings - Front or Rear - Exterior/Roof/Reseal/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-03-03 16:51:43 :: THE DICOR WAS WET WHEN THE UNIT WAS DELIVERED AND HAS RIPPLED Roof needs dicor applied over the voids Applied dicor to the roof as needed.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$92.50

Appr Labor Amt \$37.00

after review, please clean off the sealant on the vent cap all areas appears to be sealed
no reseal needs to be done at this time
thank you

Submitted	Labor Amt	\$148.00	Approved	Labor Amt	\$92.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$148.00		Total	\$92.50

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.