



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79078
Promised Date:

CUSTOMER WORK ORDER

WO #: 79078

Customer: 56521 - MCREYNOLDS,
ROBERT & SARA - 270-922-1775

Tag:

Author: BH

Location: 0305 CHECK PREAUTH

Stock #: 11672

Stock Desc: 2026 TT KEYSTONE
SPRINGDALE 2300BH

Chassis #: 4YDTSGK23T7101251

Serial #: 4YDTSGK23T7101251

Mileage:

Licence:

Invoice #:

Date In: 20 FEB 26

Promised: 28 FEB 26

Date Sched:

Completed: 28 FEB 26

Warr. Date: 28 FEB 26

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights work properly tail lights work properly except right rear it has 3 lights burning out. Brakes and Emergency Brakes work properly. Exterior inspection looks good roof inspection looks good. Awning fabric and hardware looks and works properly Awning lights work properly. Hooked up to city water and flushed out all the lines. Water heater works properly stove works properly microwave works properly refrigerator works properly ac works properly furnace works properly door side compartment wood pannel was loose so i shot a couple stapels in it. Good to go. And side panel of couch was loose so i shot some stapels in it. Its good to go now

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: Hitch work
Swap hitch

CORRECTION: Installed the hitch brakets on the camper and had to move the ground wire forward because it was located right where the hitch brakets needed to go. And put the rest of the hitch in side compartment.
Swapped hitch

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C



Customer #: 56521
MCREYNOLDS, ROBERT &
SARA



W/O: 79078
Promised Date: 28 FEB 26



Customer #: 56521
MCREYNOLDS, ROBERT &
SARA



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #E2:				0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Job #MONSTER - Internal

COMPLAINT: MONSTER SEAL IN 4 TIRES

CAUSE: Install monster seal

CORRECTION: Let air out of all 5 tires and pumped monster seal in. Put valve cores in and put correct air pressure in all 5 tires. And put monster seal stickers on unit. Good to go

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Subtotal for Job #MONSTER:			0.00

Job #1 - Internal

WASHBAY -- MAXXGAURD

Subtotal for Job #1: 0.00

Job #2 - Internal

3 MONTHS FREE STORAGE

Other Services

Code	Description	Qty	Price	Total
STORAGE	MONTHLY STORAGE FEE	3.00	N/C	N/C
Subtotal for Job #2:				0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Turned valve to winterize and pumped winterize solution through the water pump to bathroom shower cold and hot until solution was there then repeated for toilet bathroom faucet kitchen faucet outside shower. And depressed city water inlet drained water heater. And drained black tank and gray tank and fresh tank. Used 2 gallons of winterize solution

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C



W/O: 79078
Promised Date: 28 FEB 26



Customer #: 56521
MCREYNOLDS, ROBERT &
SARA



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #3 - Warranty

COMPLAINT: REAR TAILLIGHT NOT WORKING CORRECTLY

CAUSE: Replace right rear tail light

CORRECTION: On inspection of this unit found that three of the led lights were not working. So i put a parts request in for a new. And it came in so i removed the old light znd replaced it with a new one and it sealed it with clear silicone. I tested it and it works properly. good to go now.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	1.80
Z990	MISCELLANEOUS REPAIR	JTW	34.20

Parts

Part #	Description	Qty	Price	Total
6875	Light - Tail - LED - w/Reflector - P	1.00	12.05	12.05

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-LIGHT	1.00	12.14	12.14

Subtotal for Job #3: 60.19

Job #4 - Warranty

COMPLAINT: REPLACE INTERIOR LIGHT

CAUSE: Light flickering in Living/Dinning area

CORRECTION: Replaced flickering shorting out light.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JRK	36.00

Parts

Part #	Description	Qty	Price	Total
479579	LED - Mushroom Light - Ultra Bright - w/Switch	1.00	2.30	2.30

Subtotal for Job #4: 38.30

Parts Total: 14.35
Labour Total: 72.00
Sublet Total: 0.00
Extras Total: 12.14
WORK ORDER TOTAL: 98.49

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer Signature : _____

Date: 05 Mar 2026

W/O: 79078
Promised Date: 28 FEB 26



Customer Work Order

Customer #: 56521
MCREYNOLDS, ROBERT &
SARA

