

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79094
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 40865 - DANA BRAMES
Address: 214 S. 17TH ST. PETERSBURG, IN

47567

Phone: 812-789-3091

Stock Number: 11623 - 2026 CHEROKEE GREY WOLF 27LH 4X4TCKC21TX166918

VIN: 4X4TCKC21TX166918 HIN:

SER#: 4X4TCKC21TX166918

Mileage: 0

Work Order Comp: 28 FEB 26

Auth. No:

Dealer #:

Warr. Date: 21 FEB 26

Work Order Date: 23 FEB 26

Inv #: 427074

WO # Job # Description JOB INFORMATION

79094 2 ENTRY DOOR NOT CLOSING
The door is bent and will not latch.
I found that the only thing that is holding the door closed is
the lend a hand folded in front of the door. I pushed on the door
latch and it will not latch. I put a straight edge on the door
face and found the door to be bent. I blocked the top and bottom
of the door to adjust the center. I was able to get the door
straight again. I tested the door fitment many times to make sure
that it would open and close properly. The door is now working as
it should.

79094 3 STOVE WILL NOT LIGHT, NO LP
Gas line was pulled too tight behind the stove top.
The stove would not light and if it did, the flame was very weak.
I started by checking if the stove would lite with the slide room
in and out. This did not change any of the symptoms. I took the
lower valance off of the slide room to check the gas line. I took
the drawers out to check the gas line. The last thing I checked
was the hole behind the stove. The gas line was folded very
tight. I could move the gas line behind the microwave and the
flame of the stove would get bigger and smaller depending on the
position. I freed up the gas line so that it was not so tight
behind the stove top. I pulled a little more hose from under the
drawers to go behind the microwave. With the extra slack behind
the microwave, the stove is lighting everytime. I put the
cabinets and cooktop back together and tested the system again.

Claim : 79094

WO # Job # Description JOB INFORMATION

The stove is now working as it should.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISC LABOUR CODE (EXTERNAL) 0.60 185.00 111.00

Z990 3 MISC LABOUR CODE (EXTERNAL) 1.20 185.00 222.00

Parts Total: 0.00

Labour Total: 333.00

Sublet Total: 0.00

Extras Total: 0.00

>>>> Claim Total: 333.00

Customer Signature: _____

Date: _____