

# FOREST RIVER WARRANTY CLAIM FORM

|                        |          |                   |                   |
|------------------------|----------|-------------------|-------------------|
| DEALER ACCOUNT #       | 0005106  | CLAIM STATUS      | Authorized        |
| BASDEN RV CENTER INC   |          | CLAIM             | 2599268           |
| DBA AMERICAN RV CENTER |          | CLAIM ORIGIN      | WEB               |
| 600 E BASELINE ROAD    |          | ORIGINAL CLAIM ID |                   |
| EVANSVILLE, IN 47725   |          | VIN               | 5ZT2CANB3TU048250 |
| USA                    |          | CHASSIS VIN       |                   |
|                        |          | MILEAGE           | 0                 |
| Labor rate:            | \$185.00 | SITE/WAREHOUSE    | 103 / 103         |
| OWNER INFORMATION      |          | ITEM #            | CAT243RBSLE       |
|                        |          | DEALER RO #       | 79106             |
|                        |          | CLAIM START DATE  | 03/04/2026        |
|                        |          | CLAIM END DATE    | 01/01/1900        |

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

|         |                                                                                                                                                                                                                                                                                                 |                                                                                 |                |         |
|---------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|----------------|---------|
| Line# 1 | Operation Code                                                                                                                                                                                                                                                                                  | Operational Description                                                         |                |         |
|         | 30-92-01-00-001163                                                                                                                                                                                                                                                                              | Ceiling Fan Light Globe - Interior/Interior Miscellaneous/Replace/No Tread Code |                |         |
|         | Complaint, Cause, Correction                                                                                                                                                                                                                                                                    |                                                                                 |                |         |
|         | Original Note : bhoffman@americanrvcenter.com, 2026-03-04 14:24:55 :: LIGHT ABOVE THE KITCHEN SINK NEEDS FIXE D Light was loose Tightened the 3 screws up and put cover bak on. Good to go Additional Note : bhoffman@americanrvcenter.com, 2026-03-04 14:26:57 :: THIS IS NOT REPLACE ONLY FIX |                                                                                 |                |         |
| Model#  | Dlr Sub Hrs                                                                                                                                                                                                                                                                                     | 0.10                                                                            | Sub Labor Amt  | \$18.50 |
| Serial# | Appr Hrs                                                                                                                                                                                                                                                                                        | 0.10                                                                            | Appr Labor Amt | \$18.50 |
|         | Notes                                                                                                                                                                                                                                                                                           |                                                                                 |                |         |

### Labor

|         |                                                                                                                                                                                                     |                                                                                     |                |         |
|---------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------|---------|
| Line# 2 | Operation Code                                                                                                                                                                                      | Operational Description                                                             |                |         |
|         | 70-157-24-00-001849                                                                                                                                                                                 | Exterior Refrigerator Door - Appliances/Refrigerator (Dometic)/Repair/No Tread Code |                |         |
|         | Complaint, Cause, Correction                                                                                                                                                                        |                                                                                     |                |         |
|         | Original Note : bhoffman@americanrvcenter.com, 2026-03-04 14:51:11 :: FREEZER INSIDE IS HITTING THE TRAVEL LOCK Freezer door hitting travel lock Put nylon washer on hinge door works properly now. |                                                                                     |                |         |
| Model#  | Dlr Sub Hrs                                                                                                                                                                                         | 0.10                                                                                | Sub Labor Amt  | \$18.50 |
| Serial# | Appr Hrs                                                                                                                                                                                            | 0.10                                                                                | Appr Labor Amt | \$18.50 |
|         | Notes                                                                                                                                                                                               |                                                                                     |                |         |

### Labor

|         |                                                                                                                                                                                                   |                                                                               |                |         |
|---------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------|----------------|---------|
| Line# 3 | Operation Code                                                                                                                                                                                    | Operational Description                                                       |                |         |
|         | 20-69-02-17-000708                                                                                                                                                                                | Compartment Door Lock or Slam Latch - Exterior/Compartment Doors/Adjust/Latch |                |         |
|         | Complaint, Cause, Correction                                                                                                                                                                      |                                                                               |                |         |
|         | Original Note : bhoffman@americanrvcenter.com, 2026-03-04 14:52:42 :: THE OUTDOOR KITCHEN LATCH IS BENT Outdoor kitchen door latch bent Took latch off and straighted it. Door works properly now |                                                                               |                |         |
| Model#  | Dlr Sub Hrs                                                                                                                                                                                       | 0.20                                                                          | Sub Labor Amt  | \$37.00 |
| Serial# | Appr Hrs                                                                                                                                                                                          | 0.20                                                                          | Appr Labor Amt | \$37.00 |
|         | Notes                                                                                                                                                                                             |                                                                               |                |         |

### Labor

|         |                                                                                                                                                                                                                           |                                                                   |  |  |
|---------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|--|--|
| Line# 4 | Operation Code                                                                                                                                                                                                            | Operational Description                                           |  |  |
|         | 30-100-12-00-001056                                                                                                                                                                                                       | Backsplash - Interior/Cabinetry/Resecure or Tighten/No Tread Code |  |  |
|         | Complaint, Cause, Correction                                                                                                                                                                                              |                                                                   |  |  |
|         | Original Note : bhoffman@americanrvcenter.com, 2026-03-04 14:53:30 :: BACKSPLASH IS COMING LOOSE Backsplash coming off Cleaned area behind backsplash and put adhesive on it and pushed it back to the wall. Its good now |                                                                   |  |  |

|         |             |      |                |         |
|---------|-------------|------|----------------|---------|
| Model#  | Dlr Sub Hrs | 0.10 | Sub Labor Amt  | \$18.50 |
| Serial# | Appr Hrs    | 0.10 | Appr Labor Amt | \$18.50 |
| Notes   |             |      |                |         |

|           |                 |         |          |                 |         |
|-----------|-----------------|---------|----------|-----------------|---------|
| Submitted | Labor Amt       | \$92.50 | Approved | Labor Amt       | \$92.50 |
|           | Parts & Freight | \$0.00  |          | Parts & Freight | \$0.00  |
|           | Total           | \$92.50 |          | Total           | \$92.50 |

|           |      |
|-----------|------|
| DEALER    | DATE |
| SIGNATURE |      |

I certify that I have performed these repairs consistent with Forest River Policies.

|           |      |
|-----------|------|
| CUSTOMER  | DATE |
| SIGNATURE |      |

All repairs described have been inspected and are satisfactory.