



Pre-Authorization

Pre-Authorization number	PREAUTH830 Reference no.79151 94 (PA03974984	Status	Approved
--------------------------	--	--------	----------

Servicing Dealer 1194 Name Basden's American RV Address 600 E Baseline Rd
Evansville, IN 47725 VIN 4YDTCGM26TV505361 Retail sold on

Root		Approved		Actual		Base		Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	hours	
3201806A	Decorative Wood Trim - Repair - per piece	0	0.3	0.3		1	0.1	Complaint: 3 DIFFERANT AREAS NEED TO HAVE THE TRIM FIXED Cause: Wood trim glue failing Correction: Peeled trim to flatten out. Reinstalled using staples. Covered staples in wood putty
2106414A	Slide Out Box with Metal Exterior, Metal Siding	0	0.2	0.2		1	0.5	Complaint: OFF DOOR SIDE SLIDE JWRAP IS BOWING NEEDS A STRAP TO HOLD IT IN PLACE Cause: Slideroom j wrap has a lot of flex Correction: We and a support from j wrap to bottom of slideroom. And it took the flex out.
1204116B	Slide Out Drive Bracket Assembly	0	0.4	0.4		1	0.5	Complaint: THE BRACKET ARE LOOSE UNDER THE SLIDE ROOM THAT MOVES THE ROOM IN AND OUT Cause: Slideroom bolts Correction: Checked slideroom and tightened up the 4 bolts and the jam nut. Slideroom works properly
2302202A	Compartment Door	0	0.2	0.2		1	0.2	Complaint: DOOR SIDE FRONT COMPARTMENT DOOR HAS SCRATCHES Cause: Door hinge scratched by door Correction: Applied white touch up paint to scratches
Pre-Authorization number: PREAUTH83094				1.1				

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.