

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79170
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER

Customer: 1000 - BASDEN'S AMERICAN RV

Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11724 - 2026 CATALINA 333DORM 5ZT2CAYB0TX037068

VIN: 5ZT2CAYB0TX037068 HIN:

SER#: 5ZT2CAYB0TX037068

Mileage: 0

Work Order Comp: 24 MAR 26

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 04 MAR 26

Inv #: 427825

WO # Job # Description JOB INFORMATION

WO #	Job #	Description	JOB INFORMATION
79170	2	THE FRIDGE HAS A BIG SCRATCH ON IT Scratch Unscrewed the fridge then pulled out the fridge with help from another tech. Disconnected the power from the fridge. Got the fridge out of the camper. Unboxed the new fridge. Mounted the supplied mounting brackets to the fridge. Took the fridge in the camper with help from another tech. Connected the 12 v wires to the fridge then set in the cabinet and mounted to it. Pulled off the packing tape. Verified the fridge was cooling.	
79170	8	THE TOP WOOD IN THE BATHROOM NEAR THE MIRROR IS DAMAGE Cabinet Removed cabinet door. Removed lower panel under cabinet. Removed screws holding cabinet. Removed bathroom door and frame. Removed cabinet. Removed 3/4" blocking. Removed shelf. Removed inside panel. Removed damaged stile. Cut and installed stile. Put panel back. Put shelf back on. Cut and installed new 3/4" blocking. Put cabinet back in. Put door frame back on.	
79170	3	TRIM ABOVE THE FRIDGE IS COMING OFF Trim pulled off Tapped trim back into place	
79170	4	THE DOORS UNDER THE FIREPLACE ARE TOUCHING AND WONT CLOSE Left side door mounted too far inward Moved left side door out and tested fitment	

Claim : 79170

 WO # Job # Description JOB INFORMATION

79170	5	DIMMER SWITCH IS COMING OFF THE WALL Screws stripped Installed new screws and two extra
79170	6	REAR SCREEN DOOR IS RUBBING Door needed adjusting Adjusted door to the point it no longer rubs
79170	9	LEAK UNDER THE KITCHEN SINK Loose P-trap and sink fittings Tightening fittings and tested
79170	10	TRIM ON THE LEFT SIDE OF THE DINNETE IS COMING OFF Screws stripped out of wood Relocated and Installed new hardware
79170	11	ADJUST 3 BEDROOM SLIDING DOORS Doors uneven and contacting the door guides Left bunk door raised on left side hanger. Right bunk door raised on left side hanger. Master bedroom door raised on both hangers

 Part No Job# Description PARTS Qty Price Total

 F100729508 2 REFRIGERATOR, GE 10 CU FT RH TOP 1.00 974.36 974.36
 F100285188 8 3" CABINET STILE 1.00 10.75 10.75

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.58 195.00 113.10
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.42 195.00 81.90
 Z990 8 MISC LABOUR CODE (EXTERNAL) 1.00 195.00 195.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.30 195.00 58.50
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.25 195.00 48.75
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.20 195.00 39.00
 Z990 9 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 10 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 10 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 10 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 11 MISC LABOUR CODE (EXTERNAL) 0.60 195.00 117.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 2 FREIGHT-REFER 1.00 213.12 213.12

Claim : 79170

 Excode Job# Description EXTRAS Qty Price Total

Parts Total: 985.11
 Labour Total: 711.75
 Sublet Total: 0.00
 Extras Total: 213.12

>>>> Claim Total: 1,909.98

Customer Signature: _____

Date: _____