



Pre-Authorization

Pre-Authorization number	PREAUTH838 35 (PA03975684	Reference no.79171	Status	Approved
--------------------------	---------------------------------	--------------------	--------	----------

Servicing Dealer 1194 Name Basden's American RV Address 600 E Baseline Rd
Evansville, IN 47725 VIN 4YDFCGP22T2505139 Retail sold on

Root		Approved Actual				Base	Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	
3200102A	Door - Interior Hinged - Repair	0	0.2	0.2		1	Complaint: THE BUNK DOOR TRIM IS COMING OFF Cause: During PDI, it was found that the bunk room door trim adhesive had failed causing the trim to bow out. Tech recommends stapling trim into place Correction: Stapled trim back into place
3201902A	Mirror - Repair	0	0.2	0.2		1	Complaint: BATHROOM MIRROR IS SILICONE ON IT AND NEEDS TO BE REMOVED Cause: During PDI, it was found that the bathroom, mirror had excess silicone on it. Tech recommends removing excess silicone Correction: Gently removed excess silicone from mirror
Pre-Authorization number: PREAUTH83835				0.4			

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.