



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79191
Promised Date:
21 MAR 26

CUSTOMER WORK ORDER

WO #: 79191

Customer: 1000 - BASDEN'S AMERICAN

RV -

Tag:

Author: BJW

Location: 0313 CHECK PREAUTH

Stock #: 11679

Stock Desc: 2026 TT COACHMEN

CATALINA 281QBUNK

Chassis #: 5ZT2CATB8TN302287

Serial #: 5ZT2CATB8TN302287

Mileage: 0

Licence:

Invoice #:

Date In: 06 MAR 26

Promised: 31 MAR 26

Date Sched:

Completed: 13 MAR 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: A CUSTOMER CAME IN AND ADVISED SERVICE WRITERS THAT THIS UNIT HAD WATER STANDING IN THE FLOOR DERECTLY BELOW THE AIR CONDITIONER. WE HAVE HAD RAIN MORE THAN ONE DAY THIS WEEK.

CAUSE: Water leaking under roof ac

CORRECTION: Took trim cover off ac unit and it had water in it. So i did a water test with the hose and sprayed the roof top unit. And theni checked the 4 main bolts that hold the ac until to the inside bracket. Ben got me the torque spec on the bolts and the two front bolts were close but the two back bolts were not close the being tight. So i torqued all 4 bolts and put inside trim cover back on.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	58.50
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	68.25

Subtotal for Job #1: 126.75

Parts Total: 0.00
Labour Total: 126.75
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 126.75

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 13 Mar 2026



Customer #: 1000
BASDEN'S AMERICAN RV,

