

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79216
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11722 - 2026 CHEROKEE GREY WOLF 26DBH 4X4TCKB22TK099373
VIN: 4X4TCKB22TK099373 HIN: SER#: 4X4TCKB22TK099373
Mileage: 0 Work Order Comp: 13 MAR 26
Auth. No: Dealer #:
Warr. Date: Work Order Date: 10 MAR 26 Inv #: 427341

WO # Job # Description JOB INFORMATION

79216 5 THE SHOWER HEAD IS MISSING A BUTTON
During PDI, it was discovered that the curb side outside shower head was missing a button to cut water supply on and off. Tech recommends replacement
Removed and replaced curb side outside shower head and tested. No leaks present

79216 1 3 SET OF DOORS IN THE KITCHEN ARE TOUCHING AND WILL NOT CLOSE ALL THE WAY
During PDI, it was found that the kitchen cabinet doors were all contacting each other on closing. Tech recommends spacing the doors out fro, each other slightly to allow for easy opening and closing
Spaced all three sets of doors apart and verified fitment

79216 2 THE FRONT SCREEN DOOR WILL NOT LATCH WITH OUT FORSE
During PDI, it was found that the front screen door would not latch without force. Tech recommends adjusting screen door striker forward to alleviate this issue
Moved front screen door striker plate forward and tested. Screen door now shuts as intended

79216 3 IN THE REAR COMPARTMENT THERE IS UNDERBELLY INSIDE
During PDI, it was found that the rear street side compartment had excess underbelly material showing through the wall. Tech recommends cutting the material cleanly at the wall

Claim : 79216

 WO # Job # Description JOB INFORMATION

 Cut and removed excess underbelly material from rear street side
 compartment

79216 4 THE AWNING FABRIC HAS A LOT OF DIECOR ON IT
 During PDI, it was found that the awning had a large amount of
 excess dicor on the fabric. Tech recommends removing this.
 Removed dicor and cleaned area thoroughly

 Part No Job# Description PARTS Qty Price Total

 AMBCRD-U-HD60 5 PW ULTRA 1-FUNCTION SHOWER HEAD O 1.00 16.89 16.89

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.30 195.00 58.50
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.10 0.20 0.02
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.10 0.20 0.02
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.15 195.00 29.25
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.15 195.00 29.25

Parts Total: 16.89
 Labour Total: 136.54
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 153.43

Customer Signature: _____

Date: _____