

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2608251
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKB22TK099373
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$195.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT26DBH-94
		DEALER RO #	79216
		CLAIM START DATE	03/12/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-100-02-00-003062	Operational Description Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-03-12 16:33:50 :: 3 SET OF DOORS IN THE KITCHEN ARE TOUCHING AND WILL NOT CLOSE ALL THE WAY During PDI, it was found that the kitchen cabinet doors were all contacting each other on closing. Tech recommends spacing the doors out fro, each other slightly to allow for easy opening and closing Spaced all three sets of doors apart and verified fitment	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.30	\$58.50
Serial#	Appr Hrs	Appr Labor Amt
	0.30	\$58.50
Notes	thank you	

Labor

Line# 2	Operation Code 20-66-02-00-000678	Operational Description Screen Door - Exterior/Entry Doors/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-03-12 16:36:08 :: THE FRONT SCREEN DOOR WILL NOT LATCH WITH OUT FORSE During PDI, it was found that the front screen door would not latch without force. Tech recommends adjusting screen door striker forward to alleviate this issue Moved front screen door striker plate forward and tested. Screen door now shuts as intended	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$39.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$39.00
Notes		

Labor

Line# 3	Operation Code 10-9-15-00-000168	Operational Description Polymax Underbelly - Frame & Chassis/Levelers, Underbelly/Repair or Replace/ No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-03-12 16:37:03 :: IN THE REAR COMPARTMENT THERE IS UNDERBELLY INSIDE During PDI, it was found that the rear street side compartment had excess underbelly material showing through the wall. Tech recommends cutting the material cleanly at the wall Cut and removed excess underbelly material from rear street side compartment	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.15	\$29.25
Serial#	Appr Hrs	Appr Labor Amt
	0.15	\$29.25
Notes	thank you	

Labor

Line# 4	Operation Code 20-77-24-00-000754	Operational Description Awning Fabric - Dometic A&E - Exterior/Awnings - Electrical (Dometic A & E)/
---------	---	--

Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2026-03-12 16:38:20 :: THE AWNING FABRIC HAS A LOT OF DIECOR ON IT During PDI, it was found that the awning had a large amont of excess dicor on the fabric. Tech recommends removing this. Removed dicor and cleaned area thoroughly

Model# NA Dlr Sub Hrs 0.15 Sub Labor Amt \$29.25
Serial# NA Appr Hrs 0.15 Appr Labor Amt\$29.25

Notes
thank you

Labor
Line# 5

Operation Code Operational Description
60-141-01-00-001618 Shower Head, Hose Assembly - Plumbing/Shower, Tub Surround/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2026-03-12 16:39:46 :: THE SHOWER HEAD IS MISSING A BUTTON During PDI, it was discovered that the curb side outside shower head was missing a button to cut water supply on and off. Tech recommends replacement Removed and replaced curb side outside shower head and tested. No leaks present

Model# Dlr Sub Hrs 0.10 Sub Labor Amt \$19.50
Serial# Appr Hrs 0.10 Appr Labor Amt\$19.50

Notes

Submitted	Labor Amt	\$175.50	Approved	Labor Amt	\$175.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$175.50		Total	\$175.50

DEALER DATE
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER DATE
SIGNATURE
All repairs described have been inspected and are satisfactory.