



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79245
Promised Date:
24 MAR 26

CUSTOMER WORK ORDER

WO #: 79245 (Appointment Date: 13 MAR 2026 - Time: 10:30am)

Customer: 56566 - OLDHAM, JACE -

Tag:

Author: BJW

Location: 0313 CHECK STATUS WITH
CCV

Stock #:

Stock Desc: 2020 TT KEYSTONE

HIDEOUT

Chassis #:

Serial #: 4YDT31829L7242973

Mileage:

Licence:

Invoice #: 427382

Date In: 13 MAR 26

Promised: 31 MAR 26

Date Sched:

Completed: 13 MAR 26

Warr. Date:

Job #2 - External

COMPLAINT: CUSTOMER CAN SMELL LP INSIDE WHEN RUNNING THE WATER HEATER

CAUSE: Lp smell in unit.

CORRECTION: Brought unit in. Ran lp on water heater. Looked for leaks around water heater and could not find leak at water heater. Went to manifold and other lp fixtures and checked for lp leaks. Could not find leak. Ran lp drop test. Start pressure is 19iwc. 50% with water heater and furance is 11iwc. Lock up is 16iwc. Ran leak test at 8iwc for 5mins. No leaks found. Looked inside at water heater and saw lots of build up and mud dobber inside water heater. Cleaned out and ran again, water heater burns better.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #REGULATOR - Warranty

COMPLAINT: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414

SECTION:71 COMPONENT:414 OPERATION:7141442B

CAUSE: Recall

CORRECTION: Inspected regulator and it is not in the date code to be recalled and replaced.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	54.00

Subtotal for Job #REGULATOR: 54.00

Job #3 - External

COMPLAINT: DURING INSPECTION OF WATER HEATER AND LP SYSTEM, TECH FOUND THAT THE CO2 DETECTOR WAS MANUFACTURED IN 2018 AND IS DUE FOR REPLACEMENT.

CAUSE: Replace lp decetor

CORRECTION: Went to unit and checked lp detector. Saw it had expired. Placed parts request for new detector. Recieved new detector. Pulled off wall and cut wires to it. Rewire new detector in and tested. New



Customer #: 56566
OLDHAM, JACE

lp detector works. Placed wires in wall and screwed to wall.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
09-1381	BLK UNIVERSAL LP DETECTOR	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Parts Total: 0.00
Labour Total: 54.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 54.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 Mar 2026

W/O: 79245
Promised Date: 31 MAR 26



Customer #: 56566
OLDHAM, JACE

