

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2612995
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZTCPRN01SP809442
USA		CHASSIS VIN	W1X8N33Y7PN233328
		MILEAGE	5648
Labor rate:	\$195.00	SITE/WAREHOUSE	215 / 215
OWNER INFORMATION		ITEM #	PRC24MB
DANIEL BUGHER		DEALER RO #	79283
8096 WYNGATE CIR		CLAIM START DATE	03/18/2026
Newburgh, IN 47630		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	06/30/2025	WARRANTY EXPIRATION DATE	06/30/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description	
	30-102-12-00-002691	Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2026-03-18 11:13:43 :: THE PANEL BETWEEN THE REFRIGERATOR AND THE REAR SIDE OF THE SLIDE ROOM IS WARPED. THIS IS THE PANEL THAT HAS THE THERMOSTAT ON IT. COME GET WRITER BEFORE RUNNING ROOM OUT BECAUSE IT WILL CATCH THE THERMOSTAT AND RIP IT OFF THE WALL WHEN THE ROOM IS RAN OUT IF SOMEONE ISN'T THERE TO HELP GUIDE IT. Ran the slideroom out with help from another tech because of slideroom hits the thermostat. Took pictures of the warped wall. Unscrewed the thermostat and lp detector from the panel. Disconnected the power from them. Found the panel was to tall causing the panel to bow out. Took the panel to the table saw and shaved a blade width off the bottom. Set panel up to check clearance. Added more studs behind the panel so the thermostat was solid. Connected the thermostat and lp detector and stapled the panel back up.		
	Model#	Dlr Sub Hrs	Sub Labor Amt
		1.70	\$331.50
	Serial#	Appr Hrs	Appr Labor Amt
		1.70	\$331.50
	Notes		
	ok.gf		

Labor

Line# 2	Operation Code	Operational Description	
	30-102-01-00-001101	Slide Out Fascia, each section - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2026-03-18 11:34:33 :: HAVE TO REMOVE THE SLIDE FACIA TO INSTALL WALL PANEL BACK TOO Additional Note : bhoffman@americanrvcenter.com, 2026-03-18 11:35:30 :: REMOVE AND REINSTALL AFTER STAPLING WALL PANEL BACK		
	Model#	Dlr Sub Hrs	Sub Labor Amt
		0.50	\$97.50
	Serial#	Appr Hrs	Appr Labor Amt
		0.50	\$97.50
	Notes		

Submitted	Labor Amt	\$429.00	Approved	Labor Amt	\$429.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$429.00		Total	\$429.00

DEALER	DATE	CUSTOMER	DATE
---------------	-------------	-----------------	-------------

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

SIGNATURE

All repairs described have been inspected and are satisfactory.