

Completed : 09 MAR 21 Customer : 50914 - ULRICH, ROBERT M. - 812-449
Licence # : Invoice # :
Stock No : 10637 Description : 2021 TT RIVERSIDE RV RETRO 189R
Tag : Date In : 22 FEB 21 Mileage : 0
Author : BH Promised : 04 MAR 21
Location : 0305 DELIVERY Date Sched :
Serial# : 59CCG2329ML003608 Chassis# : 59CCG2329ML003608
Warr. Date : Cust PO# :
Print Date : 12 MAR 21

Job # Description JOB INFORMATION Type Bill To *****
BUNK COMPLAINT: PRE DELIVERY INSPECTION NEW BUNKHOUSE
CAUSE: CHECKED RUNNING LIGHTS, CHECKED TIRE

BUNK COMPLAINT: FINAL PDI NEW BUNKHOUSE
CAUSE: final pdi
CORRECTION: checked 12 volt system, pressurized
water system, installed battery and
battery box, checked interior and
exterior lights, checked appliances.
checked performed lp leak test. checked
for leaks in plumbing and water system.
COMPLAINT: RECEIVER - UNIVERSAL SUV
CORRECTION: CHANGED UNIVERSAL RECEIVER ON REAR OF
JEEP.
COMPLAINT: 10K E2 EQUALIZER HITCH
CAUSE: e2 hitch install
CORRECTION: mounted brackets and set to correct
length. moved breakaway switch to
provide clearance
COMPLAINT: BRAKE CONTROL & WIRING - VAN, SUV & CAR
CORRECTION: INSTALLED BRAKE CONTROL AND WIRING.
DEAL# DO I

BCW COMPLAINT: INSTALLED A 7-WAY PLUG ON REAR BUMPER.
HAD TO RUN CHARGE WIRE AND BRAKE WIRE TO
NEW 7-WAY ON BUMPER. INSTALLED A BREAKER
UNDER THE HOOK FOR THE CHARGE WIRE AND
BRAKE CONTROLER. WIRED UP BRAKE
CONTROLER TO BRAKE SWITCH.
DEAL# DO I
DELU DELUXE STARTER KIT

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200
WORK ORDER # 63433

Work Order : 63433

Job # Description JOB INFORMATION Type Bill To

WALK COMPLAINT: WALK THRU
CORRECTION: DONE EF
PRE-D I PDI
49672 RIVER

1
CAUSE: winterization hose is hooked up to city
water inlet
CORRECTION: removed winterization hose from city
inlet and secure correct hose to inlet.
COMPLAINT: THE TRIM IN THE LIVING ROOM IS HANGING
DOWN
49672 RIVER

2
CAUSE: trim hanging in living room
CORRECTION: secure trim with staples
COMPLAINT: THE TRIM IN THE BATHROOM IS LOOSE
trim in bathroom is loose
CAUSE: secured trim with staples
CORRECTION: THE CAULKING NEXT TO THE STOVE IS
MISSING
49672 RIVER

3
CAUSE: caulking next to stove is missing
CORRECTION: applied caulking as needed.
COMPLAINT: THE TRIM IN THE COMPARTMENT IS LOOSE
front compartment has panel that is
loose.
49672 RIVER

4
CAUSE: panel did not have any framing to
support panel. took a piece of trim and
stapled to the panel that was loose and
the panel next to it to hold in place.
COMPLAINT: THE BLACK TANK FLUSH VALVE IS HOOKED UP
BACKWARDS.
CAUSE: balck tank flush valve is hooked up
backwards.
CORRECTION: reversed water lines on flush valve.

Job # Part No Description PARTS Bill to Qty Price

BUNKH 13034 55362 STD BATTERY I-PDI 1 13.99
BUNKH 14-8205 LEVEL STICK-ON 085 I-PDI 1 12.99
BUNKF DC-24 ADVANCE GROUP 24 D I-PDI 1 126.99
3002 13048 93-98 JEEP GRAND C I-DO 1 275.00
E2 14-1641 1000# E2 TRUNION H I-DO 1 275.00
BCWV 14636 7WAY PLASTIC CAR E I-DO 1 488.00
BCWV 19-0938 9 WAY CONNECTOR - I-DO 1 7.99
BCWV 19-1441 16-3030 30A CIRCUIT I-DO 1 1.99
BCWV 17-0081 #51120 BRAKE CONTR I-DO 1 5.99
DETX 13-0181 40274 2-PLY TST TO I-DO 1 76.99
DETX 41559 41559 15-PK TST LA I-DO 1 5.99
DETX 41559 41559 15-PK TST LA I-DO 1 14.99
DETX 40052 40052 BRASS W.P. R I-DO 1 14.99
DETX 14240 55165 PIGTAIL 30A I-DO 1 14.99
DETX 4943 50' MARINE WATER H I-DO 1 44.99
DETX 600885 D04-0650 15' SILVE I-DO 1 54.99

Job#	Lab Code	Description	LABOUR	Mech Bill to	Hrs	Rate	Total
HOUSE 2990	MISC LABOUR CODE (EXTE	ZMS	I-PDI		0.27	130.00	35.10
HOUSE 2990	MISC LABOUR CODE (EXTE	ZMS	I-PDI		3.73	130.00	484.90
FINAL 2990	MISC LABOUR CODE (EXTE	ZMS	I-PDI		1.50	130.00	195.00
3002 2990	MISC LABOUR CODE (EXTE	GAH	I-DO		1.20	85.00	102.00
E2 2990	MISC LABOUR CODE (EXTE	ZMS	I-DO		0.73	85.00	62.05
E2 2990	MISC LABOUR CODE (EXTE	ZMS	I-DO		0.52	85.00	44.20
BCMV BCMV	BRAKE CONTROL & WIRING	GAH	I-DO		1.11	85.00	94.35
BCMV BCMV	BRAKE CONTROL & WIRING	GAH	I-DO		1.59	85.00	135.15
WALK 2990	MISC LABOUR CODE (EXTE	EF	I-PDI		1.50	130.00	195.00
1 2990	MISC LABOUR CODE (EXTE	ZMS	W-49672		0.20	130.00	26.00
2 2990	MISC LABOUR CODE (EXTE	ZMS	W-49672		0.10	130.00	13.00
3 2990	MISC LABOUR CODE (EXTE	ZMS	W-49672		0.10	130.00	13.00
4 2990	MISC LABOUR CODE (EXTE	ZMS	W-49672		0.10	130.00	13.00
5 2990	MISC LABOUR CODE (EXTE	ZMS	W-49672		0.10	130.00	13.00
6 2990	MISC LABOUR CODE (EXTE	ZMS	W-49672		0.10	130.00	13.00

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
HOUSE LPG		LP GAS	I-PDI		8.00	2.99	23.92
HOUSE SS		SHOP SUPPLIES	I-PDI		1.00	0.00	0.00
3002 PARTS		UNINVENTORIED PARTS	I-DO		0.00	275.00	0.00
3002 FRT		FREIGHT	I-DO		1.00	25.00	25.00
3002 SS		SHOP SUPPLIES	I-DO		1.00	35.00	35.00
BCWV SS		SHOP SUPPLIES	I-DO		1.00	20.00	20.00

CUSTOMER COMMENTS

RECEIVER BACK AT LIFT ON GREG'S RACK 2-23-21..CAM
 RECEIVER ORDERED 2-22-21. SHOULD BE HERE ON OR AROUND 2-23-21
 DH EMAILED WARRANTY AT RIVERSIDE
 AUTH 031221-2.7

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I DO	1006.90	437.75	0.00	80.00	0.00	1,524.65
I PDI	153.97	910.00	0.00	23.92	0.00	1,087.89
W 49672	0.00	91.00	0.00	0.00	0.00	91.00
Totals	1160.87	1438.75	0.00	103.92	0.00	2,703.54