



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 63474
Promised Date: 31 MAR 21

CUSTOMER WORK ORDER

WO #: 63474

Customer: 16231 - VAUGHT, BRETT A. -
812-453-3555

Tag:

Author: BH

Location: 0325 CHECKWORK

Stock #: 10105

Stock Desc: 2019 5W KEYSTONE
MONTANA HIGH COUNTRY 305RL

Chassis #: 4YDF30520KA741786

Serial #: 4YDF30520KA741786

Mileage: 0

Licence:

Invoice #:

Date In: 26 FEB 21

Promised: 31 MAR 21

Date Sched:

Completed: 23 MAR 21

Warr. Date: 14 FEB 20

Job #4 - Warranty

COMPLAINT: PIECE OF CORNER TRIM ON FRONT CAP IS
PULLING LOOSE,

CAUSE: THE CORNER PIECE IS BROKEN MATT ORDERED NEW CORNERS 1/22/21

CORRECTION: installed corners

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	BRM	65.00
Z990	MISCELLANEOUS REPAIR	BRM	0.00

Parts

Part #	Description	Qty	Price	Total
390686	Trim - Cap - Lower	1.00	9.18	9.18

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-CAPS	1.00	10.99	10.99

Subtotal for Job #4: 85.17

Job #5 - Warranty

COMPLAINT: BATHROOM STAINS BETWEEN THE SHOWER IF
CANT BE CLEANED REPLACE FOOR TO HALLWAYS

CAUSE: SLIDE ROOM WAS LEAKING ON THE REAR. LINOLEUM HAS BEEN REPLACED BEFORE IN
THE BEDROOM.

CORRECTION: I REMOVED ALL THE CABINETS AND THE BED AND CUT OUT ALL THE LINOLEUM.
REMOVED TOILET AND ALL TRIM AND THE BATHROOM DOOR I REPLACED THE LINOLEUM IN
THE BEDROOM AND REINSTALLED TRIM AND SEALED AND REPLACED THE LINOLEUM IN THE
BATHROOM AND REINSTALLED ALL REIM AND CABINETS.. I HAD TO WATER TEST THE
SLIDEROOM AND AND FOUND THE SEALS WAS NOT TOGETHER ON THE REAR SIDE SO I
SEALED THE FLAP SEALS IN THE REAR AND THE SEALS ON THE FRONT I LET SIT DURING 2
RAINS AND HAD NO WATER INSIDE ON THE FLOOR.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	36.40
Z990	MISCELLANEOUS REPAIR	BRM	115.70
Z990	MISCELLANEOUS REPAIR	BRM	423.80



Customer #: 16231
VAUGHT, BRETT A.

Z990	MISCELLANEOUS REPAIR	BRM	516.10
Z990	MISCELLANEOUS REPAIR	BRM	518.70
Z990	MISCELLANEOUS REPAIR	BRM	517.40
Z990	MISCELLANEOUS REPAIR	BRM	529.10
Z990	MISCELLANEOUS REPAIR	BRM	397.80

Parts

Part #	Description	Qty	Price	Total
616254	Linoleum - 8'2" -	14.00	10.90	152.60
554899	Trim - Base Shoe -	8.00	2.38	19.04
554812	Trim - Batten - 3.	2.00	1.73	3.46

Other Services

Code	Description	Qty	Price	Total
FRT	UPS FREIGHT - LINO AND TRIM	1.00	72.45	72.45

Subtotal for Job #5: 3,302.55

Parts Total: 184.28
Labour Total: 3,120.00
Sublet Total: 0.00
Extras Total: 83.44
WORK ORDER TOTAL: 3,387.72

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Mar 2021



Approved date 3/23/2021

4YDF30520KA741786 2/14/2020

Complaint:KRV - Changed root operation to cause. Ilioleum has what appears to be pvc glue on it. there is a dividen strip between the bedroom and hallway like it was noticed at factory but not changed out during production.

—

23.50

Include a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the