

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 63693

Completed : 31 MAR 21 Customer : 44153 - KIESLER, MICHAEL T. - 812-2
Licence # : Invoice # :
Stock No : 10685 Description : 2021 TT COACHMEN CATALINA 323BHDSC
Tag : Date In : 23 MAR 21 Mileage :
Author : BH Promised : 25 MAR 21
Location : 0325DELIVERY Date Sched :
Serial# : 5ZT2CAXB4MX021085 Chassis# : 5ZT2CAXB4MX021085
Warr. Date : 25 MAR 21 Cust PO# :
Print Date :

Job # Description JOB INFORMATION Type Bill To

FPDI COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS I PDI PRE-D
CORRECTION: FINAL PDI
CAME COMPLAINT: INSTALL WIRELESS CAMERA I DO DEALE
CORRECTION: installed camera and paired with screen
EQUA COMPLAINT: INSTALL 1000# EQUALIZER HITCH I DO DEALE
CAUSE: hitch install
CORRECTION: installed hitch head and adjusted as
needed
WALK COMPLAINT: WALK THRU I PDI PRE-D
CORRECTION: DONE EF
1 COMPLAINT: THE RED SWITCH ON THE BATTERY SHUT OFF W 10024 FORES
IS BROKEN OFF.
CAUSE: FOUND BLACK PLASTIC UNDER RED SWITCH TO
BE BROKEN.
CORRECTION: REPLACED BROKEN SWITCH WITH ONE THAT WAS
JUST A LITTLE DIFFERENT

Job # Part No Description PARTS Bill to Qty Price Total

FPDIN DC-24 ADVANCE GROUP 24 D I-PDI 1 126.99 126.99
FPDIN 5516 A10-3050FHVP 30M-5 I-PDI 1 23.99 23.99
CAMER 732556 FURRIION 5" REAR CA I-DO 1 499.99 499.99
EQUAL 710831 EQUALIZER 1000#/10 I-DO 1 677.95 677.95
1 19-0509 700RV BATTERY DISCONNECT SWIT W-10024 1 29.49 29.49

Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

DINTT PDINTT PDI - NEW TRAVEL TRAIL TEL I-PDI 2.00 130.00 260.00
AMERA Z990 MISC LABOUR CODE (EXTE TEL I-DO 0.62 120.00 74.40
AMERA Z990 MISC LABOUR CODE (EXTE TEL I-DO 0.38 120.00 45.60
R1000 Z990 MISC LABOUR CODE (EXTE ZMS I-DO 0.26 85.00 22.10
R1000 Z990 MISC LABOUR CODE (EXTE TEL I-DO 1.24 85.00 105.40
WALK Z990 MISC LABOUR CODE (EXTE EF I-PDI 1.50 130.00 195.00
1 Z990 MISC LABOUR CODE (EXTE TEL W-10024 0.30 130.00 39.00

Continued on page 2

Work Order : 63693

```

*****
Job #  Excode   Description  EXTRAS      bill to    Qty    Price    Total
*****
AMERA  SS       SHOP SUPPLIES      I-DO       0.00     0.00     0.00
R1000  SS       SHOP SUPPLIES      I-DO       1.00    11.25    11.25
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
I      DO          1177.94    247.50     0.00     11.25     0.00    1,436.69
I      PDI          150.98    455.00     0.00     0.00     0.00     605.98
W      10024         29.49     39.00     0.00     0.00     0.00     68.49

Totals          1358.41    741.50     0.00     11.25     0.00    2,111.16

```

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	535812
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAXB4MX021085
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	205 / 205
Labor rate:	\$130.00	ITEM #	ACAT323BHDSCKLE
OWNER INFORMATION		DEALER RO #	63693
MICHAEL KIESLER		CLAIM START DATE	03/24/2021
9114 SHORELINE DR		CLAIM END DATE	01/01/1900
Wadesville, IN 47638			
USA			
Retail Date of Purchase	03/27/2021	WARRANTY EXPIRATION DATE	03/27/2022

Claim Line Details

Labor

Line# 1	Operation Code 40-126-01-11-001418	Operational Description Battery Disconnect Switch - Rotary Style (picture Canada only) - Electrical/Battery Disconnect System (Motorized)/Replace/Electrical
Complaint, Cause, Correction Original Note : bjwright@americanrvcenter.com, 2021-03-24 14:18:31 :: THE RED SWITCH ON THE BATTERY SHUT OFF IS BROKEN INSPECTED SWITCH AND FOUND IT TO BE BROKEN UNDER THE RED TWIST PORTION. THE BLACK PLASTIC IS WHAT IS BROKEN WE WOULD NEED TO REPLACE THE BATTERY SHUT OFF SWITCH.		
	Model #	Dlr Sub Hrs 0.50
	Serial #	Appr Hrs 0.30
		Sub Labor Amt \$65.00
		Appr Labor Amt \$39.00
Notes		

Submitted	Labor Amt	\$65.00	Approved	Labor Amt	\$39.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$65.00		Total	\$39.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.