



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 63891
Promised Date: 30 APR 21

CUSTOMER WORK ORDER

WO #: 63891

Customer: 40775 - SCOTT, RALPH E. -
812-887-0655

Tag:

Author: BJW

Location: 0430 CALL CUSTOMER AGAIN
IF HE HASN'T PICKED UP NEW PART
YET.

Stock #: 10632

Stock Desc: 2021 TT COACHMEN
FREEDOM EXPRESS 320BHDSLE

Chassis #: 5ZT2FEXB4MW015338

Serial #: 5ZT2FEXB4MW015338

Mileage:

Licence:

Invoice #:

Date In: 12 APR 21

Promised: 30 APR 21

Date Sched:

Completed: 22 APR 21

Warr. Date: 22 OCT 20

Job #1 - Warranty

ROADSIDE REAR JACK MOTOR LOCKED UP

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	65.00

Parts

Part #	Description	Qty	Price	Total
231000	Motor; Use With Adnik Electric Stabilizer Jack Stand	1.00	76.38	76.38

Other Services

Code	Description	Qty	Price	Total
FRT	UPS - MOTOR	1.00	9.99	9.99

Subtotal for Job #1: 151.37

Parts Total: 76.38
 Labour Total: 65.00
 Sublet Total: 0.00
 Extras Total: 9.99

WORK ORDER TOTAL: 151.37

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Apr 2021



Customer #: 40775
SCOTT, RALPH E.



FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

CLAIM STATUS Authorized
CLAIM 568022
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2FEXB4MW015338
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 320 / 320
ITEM # FET320BHDSLE-320
DEALER RO # 63891
CLAIM START DATE 04/19/2021
CLAIM END DATE 01/01/1900

Labor rate: \$130.00

OWNER INFORMATION

RALPH E. SCOTT
 490 E MAYS RD
 Vincennes, IN 47591
 USA

Retail Date of Purchase 10/22/2020 **WARRANTY EXPIRATION DATE** 10/22/2021

Claim Line Details

Labor
Line# 1 **Operation Code** 10-9-01-11-000165 **Operational Description** BAL Electric Stabilizer Jack Motor (pictures) - Frame & Chassis/Levelers, Underbelly/Replace/Electrical

Complaint, Cause, Correction

Original Note : bjwright@americanrvcenter.com, 2021-04-19 14:23:27 :: THE ROADSIDE REAR JACK MOTOR LOCKED UP INSPECTED AND FOUND THE ROADSIDE REAR JACK MOTOR LOCKED UP WE WILL NEED TO REPLACE THE BAL STABILIZER JACK MOTOR

Model #	Dlr Sub Hrs	0.75	Sub Labor Amt	\$97.50
Serial #	Appr Hrs	0.50	Appr Labor Amt	\$65.00

Notes

this is to r&r the motor only.

vcb

Submitted **Labor Amt** \$97.50
 Parts & Freight \$0.00
 Total \$97.50

Approved **Labor Amt** \$65.00
 Parts & Freight \$0.00
 Total \$65.00

DEALER **DATE**
SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE
 All repairs described have been inspected and are satisfactory.