



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 63962
Promised Date: 30 APR 21

CUSTOMER WORK ORDER

WO #: 63962

Customer: 50015 - LOCKHART, RONALD

A. - 618-928-4414

Tag:

Author: BH

Location: 0429 CLOSE WO

Stock #: 10399

Stock Desc: 2020 TT COACHMEN

SPIRIT 3373RL

Chassis #: 5ZT2SBZB1LS036466

Serial #: 5ZT2SBZB1LS036466

Mileage: 0

Licence:

Invoice #:

Date In: 20 APR 21

Promised: 30 APR 21

Date Sched:

Completed: 28 APR 21

Warr. Date: 08 JUN 20

Job #1 - Warranty

COMPLAINT: WINDOW ON THE RIGHT SIDE OF THE ENTRY DOOR IS POPPED OUT ON THE BOTTOM OF THE DOOR

CORRECTION: BRING IN UNIT AND INSPECT WINDOW,, ONLY VISABLE IS THE GIMP IS OUT ANDWILL NOT GO BACK IN REPLACE GIMP

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	52.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	65.00

Subtotal for Job #1: 117.00

Parts Total: 0.00
Labour Total: 117.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 117.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer #: 50015
LOCKHART, RONALD A.

Customer Signature : _____

Date: 28 Apr 2021



FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
WASDEN RV CENTER INC		CLAIM	575534
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
		VIN	5ZT2SBZB1LS036466
EVANSVILLE, IN 47725		CHASSIS VIN	
USA		MILEAGE	0
		SITE/WAREHOUSE	220 / 220
Labor rate:	\$130.00	ITEM #	SBT3373RL
OWNER INFORMATION		DEALER RO #	63962
RONALD LOCKHART		CLAIM START DATE	04/23/2021
10785 PLANK RD		CLAIM END DATE	01/01/1900
Lawrenceville, IL 62439			
USA			
Retail Date of Purchase	06/02/2020	WARRANTY EXPIRATION DATE	06/02/2021

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description			
	20-46-24-00-000721	Window - Exterior/Windows/Repair/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2021-04-23 15:51:33 :: WINDOW GIMP IS PULLING OUT OF THE WINDOW NEED TO REPLACE THE WINDOW GIMP				
	Model #	Dlr Sub Hrs	3.00	Sub Labor Amt	\$390.00
	Serial #	Appr Hrs	0.90	Appr Labor Amt	\$117.00
	Notes				
	see 20-46-01-13-000730				

Submitted	Labor Amt	\$390.00	Approved	Labor Amt	\$117.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$390.00		Total	\$117.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	