



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 64024  
Promised Date: 15 MAY 21

## CUSTOMER WORK ORDER

WO #: 64024

Customer: 49116 - EUNICE, TINA M. -  
270-577-3796

Tag:

Author: BH

Location: 0510 VERIFY THAT FR HAS  
RECIEVED PIC OF SPEAKER

Stock #: 10876

Stock Desc: 2021 TT FOREST RIVER

CHEROKEE 324TS

Chassis #: 4X4TCKH20MX151224

Serial #: 4X4TCKH20MX151224

Mileage: 0

Licence:

Invoice #:

Date In: 26 APR 21

Promised: 15 MAY 21

Date Sched:

Completed: 30 APR 21

Warr. Date: 26 APR 21

### Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDI

CORRECTION: FILLED LP TANKS, RAN LP LEAK TEST, CHECKED TIRE PRESSURE, TORQUED LUG NUTS, CHECKED RUNNING LIGHTS, INTERIOR LIGHTS, DEWINTERIZED, FILLED HOLDING TANKS, CHECKED WATER AND PLUMBING SYSTEM FOR LEAKS, CHECKED ROOF, CHECKED ALL APPLIANCES, DOCUMENTED MODEL AND SERIAL NUMBERS FOR APPLIANCES, CHECKED ELECTRICAL SYSTEM

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z991 | MISC LABOUR CODE (INTERNAL) | ZMS      | N/C   |
| Z991 | MISC LABOUR CODE (INTERNAL) | ZMS      | N/C   |
| Z991 | MISC LABOUR CODE (INTERNAL) | ZMS      | N/C   |
| Z991 | MISC LABOUR CODE (INTERNAL) | ZMS      | N/C   |
| Z991 | MISC LABOUR CODE (INTERNAL) | ZMS      | N/C   |

#### Other Services

| Code | Description     | Qty  | Price | Total |
|------|-----------------|------|-------|-------|
| SS   | SHOP SUPPLIES   | 1.00 | N/C   | N/C   |
| LPGI | LP - UNIT SALES | 8.00 | N/C   | N/C   |

Subtotal for Job #PDINTT: 0.00

### Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FINAL PDI

CORRECTION: CHECKED ELECTRICAL SYSTEM, RUNNING LIGHTS, BRAKES, PRESSURIZED WATER SYSTEM, DRAINED ALL HOLDING TANKS, CHECKED ALL APPLIANCES, ALL OTHER LIGHTS,

#### Labor

| Code   | Description              | Mechanic | Total |
|--------|--------------------------|----------|-------|
| PDINTT | PDI - NEW TRAVEL TRAILER | ZMS      | N/C   |
| PDINTT | PDI - NEW TRAVEL TRAILER | ZMS      | N/C   |

#### Parts

| Part # | Description        | Qty  | Price | Total |
|--------|--------------------|------|-------|-------|
| 5516   | A10-3050FHVP 30M-5 | 1.00 | N/C   | N/C   |

Subtotal for Job #FPDINTT: 0.00



Customer #: 49116  
EUNICE, TINA M.

**Job #JACK - Internal**

COMPLAINT: INSTALL ELECTRIC TONGUE JACK

CAUSE: install electric tongue jack

CORRECTION: removed manual jack. installed new jack and wired to battery

| Labor Code | Description                 | Mechanic | Total |
|------------|-----------------------------|----------|-------|
| Z990       | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |

| Parts Part #            | Description        | Qty  | Price | Total |
|-------------------------|--------------------|------|-------|-------|
| 3291                    | 3500# STROMBERG EL | 1.00 | N/C   | N/C   |
| Subtotal for Job #JACK: |                    |      |       | 0.00  |

**Job #SWAP - Internal**

COMPLAINT: SWAP CUSTOMER'S HITCHWORK

CAUSE: SWAP HITCH

CORRECTION: INSTALLED HITCH FROM TRADE IN

| Labor                   |                             |          |       |
|-------------------------|-----------------------------|----------|-------|
| Code                    | Description                 | Mechanic | Total |
| Z990                    | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |
| Subtotal for Job #SWAP: |                             |          | 0.00  |

**Job #WALK - Internal**

COMPLAINT: WALK THRU

CORRECTION: DONE EF  
Estimated Amount: 180.00

| Labor                   |                             |          |       |
|-------------------------|-----------------------------|----------|-------|
| Code                    | Description                 | Mechanic | Total |
| Z990                    | MISC LABOUR CODE (EXTERNAL) | EF       | N/C   |
| Subtotal for Job #WALK: |                             |          | 0.00  |

**Job #1 - Warranty**

COMPLAINT: OUTDOOR LEFT LIGHT IN SPEAKER NOT WORKING

CAUSE: LEFT OUTDOOR SPEAKER LIGHT IS NOT WORKING.

CORRECTION: REMOVED SPEAKER. FOUND THAT THE WIRES FOR THE LIGHT ARE REVERSED.  
SWAPPED WIRES AND INSTALLED WIRE CAPS

| Labor                |                             |          |       |
|----------------------|-----------------------------|----------|-------|
| Code                 | Description                 | Mechanic | Total |
| Z990                 | MISC LABOUR CODE (EXTERNAL) | ZMS      | 13.00 |
| Subtotal for Job #1: |                             |          | 13.00 |



|                          |              |
|--------------------------|--------------|
| Parts Total:             | 0.00         |
| Labour Total:            | 13.00        |
| Sublet Total:            | 0.00         |
| Extras Total:            | 0.00         |
| <b>WORK ORDER TOTAL:</b> | <b>13.00</b> |

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 07 May 2021

Customer Order

