



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 64058
Promised Date: 25 JUN 21

CUSTOMER WORK ORDER

WO #: 64058

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:
Author: BJW

Location: 0622 CHECK STATUS WITH
ZS

Stock #: 10791

Stock Desc: 2021 5W KEYSTONE
MONTANA 3781RL

Chassis #: 4YDF37827M4703185

Serial #: 4YDF37827M4703185

Mileage: 0

Licence:

Invoice #:

Date In: 29 APR 21

Promised: 25 JUN 21

Date Sched:

Completed: 24 JUN 21

Warr. Date:



Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CAUSE: final pdi

CORRECTION: filled lp , lp leak test, checked running lights, brakes, all appliances, water and plumbing, electrical system, leveling system, checked tire pressure, torqued lug nuts, dewinterized, documented model and serial numbers,

Labor Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	14.00	N/C	N/C
Subtotal for Job #PDINFW:				0.00

Job #1 - Warranty

COMPLAINT: FRONT A/C IS NOT RESPONDING

CAUSE: BREAKER WAS TRIPPED ON FRONT A/C. A/C IS WORKING.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Subtotal for Job #1:			0.00

Job #2 - Warranty

COMPLAINT: REAR A/C IS NOT COOLING

CAUSE: BH SENT IN PREAUTH WAITING TO HEAR BACK

Labor Code	Description	Mechanic	Total
------------	-------------	----------	-------

Customer #: 1000
BASDEN'S AMERICAN RV,



e-Authorization

6/24/20 11:28:55

e-Authorization number PA02838103 Reference no: 64058
 Authorizing Name Address

Status: Approved Approved by kiddz
 VIN Retail sold on

Approved date 6/11/2021

34 Basden's American RV Basden's American RV
 600 E Baseline Rd
 Evansville, IN 47725
 4YDF37827M4703185

Job operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6101024B Drain Valves with	0.00	1.00	1.00		1	0.10	Complaint:HANDLE/ROD FOR GREY TANK OFF AND UNDERBELLY HAS TO BE PULLED DOWN TO GAIN ACCESS TO REINSTALL. Cause:INSPECTED UNIT AND FOUND HANDLE/ROD FOR GREY TANK TO BE MISSING. Correction:PULLED DOWN UNDERBELLY TO GAIN ACCESS AND REINSTALLED GREY TANK HANDLE/ROD

e-Authorization number PA02838103

1.00

For paper claims only use one pre-authorization number per warranty claim for
 please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the