



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 64356
Promised Date: 12 JUN 21

CUSTOMER WORK ORDER

WO #: 64356

Customer: 51471 - WILSON, SAMANTHA
A. - 812-449-2509

Tag:
Author: BH
Location: 0622 CHECK PERAUTH

Stock #: 10727
Stock Desc: 2021 TT KEYSTONE
SPRINGDALE 1760BH
Chassis #: 4YDT17619MW111505
Serial #: 4YDT17619MW111505
Mileage:
Licence:

Invoice #:
Date In: 07 JUN 21
Promised: 12 JUN 21
Date Sched:
Completed: 24 JUN 21
Warr. Date: 12 JUN 21

Job #BUNKHOUSE - Internal

COMPLAINT: PRE DELIVERY INSPECTION NEW BUNKHOUSE

CORRECTION: PDI

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	4.00	N/C	N/C
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #BUNKHOUSE: 0.00

Job #BUNKFINAL - Internal

COMPLAINT: FINAL PDI NEW BUNKHOUSE

CORRECTION: FPDI

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 D	1.00	N/C	N/C

Subtotal for Job #BUNKFINAL: 0.00

Job #E2 - Internal

10K E2 EQUALIZER HITCH

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 51471
WILSON, SAMANTHA A.



Z990 MISC LABOUR CODE (EXTERNAL) GAH N/C
 Z990 MISC LABOUR CODE (EXTERNAL) JP N/C

Parts

Part #	Description	Qty	Price	Total
14-5612	10K TRUNNION E2 2-	1.00	N/C	N/C
14-8608	91-00-6100 2-5/16"	1.00	N/C	N/C
Subtotal for Job #E2:				0.00

Job #DELUXE - Internal
 DELUXE STARTER KIT

Parts

Part #	Description	Qty	Price	Total
10-0281	22793 50' 5/8" DRI	1.00	N/C	N/C
40052	40052 BRASS W.P. R	1.00	N/C	N/C
13-0181	40274 2-PLY TST TO	1.00	N/C	N/C
5487	A10-1530HVP 15M -	1.00	N/C	N/C
41573	41573 10-PK TST MA	1.00	N/C	N/C
11-0018	39741 20' RHINOFLE	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Job #WALK - Internal
 COMPLAINT: WALK THRU

CORRECTION: DONE EF
 Estimated Amount: 180.00

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	EF	N/C
Subtotal for Job #WALK:			0.00

Job #1 - Warranty

COMPLAINT: THE PLUMBING VENT ON THE ROOF IS LEAKING AND PUSHED UP AND THE RUBBER ROOF IS PUSHED UP AS WELL.

CAUSE: PIPE TOO LONG AND FACTORIY PUSHED PIPE UP PUSHING VENT AND RUBBER,

CORRECTION: OPEN ACSESS PANEL UNDER BATROOM SINK, OPEN BOTTOM BUNK, CHECK PLUMBING AND THEN REMOVE VENT CAP CUT PIPE BACK TO PROPER HITH INSTALL VENT, CLOSE UP ACSESS PANELS

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	169.00
Subtotal for Job #1:			169.00

Parts Total:	0.00
Labour Total:	169.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	169.00

W/O: 64356
 Promised Date: 12 JUN 21



Customer #: 51471
 WILSON, SAMANTHA A.



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 24 Jun 2021

W/O: 64356
Promised Date: 12 JUN 21



Customer Work
Order

Customer #: 51471
WILSON, SAMANTHA A.



Pre-Authorization

6/24/20
11:59:52

Pre-Authorization number PA02856325 Reference no: 64356 Status: Approved Approved by harek
 Technician Name Address Address VIN Retail sold on Approved date 6/21/2021

34 Basden's American RV Basden's American RV 4YDT17619MW111505 6/12/2021
 600 E Baseline Rd
 Evansville, IN 47725

In Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2202615B Plumbing Vent - F	0.00	1.30	1.30		1	0.30	Complaint:THE PLUMBING VENT ON THE ROOF IS LEAKING AND PUSHED UP AND THE RUBBER ROOF IS PUSHED UP AS WELL. Cause:PIPE TOO LONG AND FACTORIRY PUSHED PIPE UP PUSHING VENT AND RUBBER, Correction:OPEN ACSESS PANEL UNDER BATROOM SINK, OPEN BOTTOM BUNK, CHECK PLUMBING AND THEN REMOVE VENT CAP CUT PIPE BACK TO PROPER HITH INSTALL VENT, CLOSE UP ACSESS PANELS

Pre-Authorization number PA02856325 1.30

For paper claims only use one pre-authorization number per warranty claim for
 Please print a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the