

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2163089
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAKB6SU044941
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	103 / 103
Labor rate:	\$170.00	ITEM #	CAT211BH-8
OWNER INFORMATION		DEALER RO #	75394
		CLAIM START DATE	01/03/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	60-138-01-00-001541	Low Point Drain - Plumbing/Drainage System/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-01-03 13:08:43 :: MISSING FRESH TANK DRAIN PLUG			
	Fresh drain plug missing Got new drain plug and put it in place			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

Labor

Line# 2	Operation Code	Operational Description		
	30-96-24-00-000969	Folding Table Leg, each - Interior/Folding Leg/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-01-03 13:11:14 :: TABLE LEG BASE BROKEN Plastic table leg broken holder I removed the table legs then removed the floor holder and replaced with new			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

Labor

Line# 3	Operation Code	Operational Description		
	70-151-01-11-002412	EverChill 110 Volt Refrigerator - Appliances/Refrigerator (House Type)/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-01-03 13:12:32 :: FREEZER DOOR HINGE IS NOT ATTACHED RIGHT Freezer door not mounted properly There is a missing bolt holding the freezer door on and the hole is stripped out so you can not thred a bolt into place			
Model#	GPV10FSNBSB	Dlr Sub Hrs	1.25	Sub Labor Amt \$212.50
Serial#	MT557920	Appr Hrs	1.25	Appr Labor Amt \$212.50
Notes				
Install damage				

Labor

Line# 4	Operation Code	Operational Description		
	50-134-01-00-001455	LP Detector - LP Gas/LP Gas System/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-01-03 13:14:26 :: LP DETECTOR IS NOT WORKING Lp detector not working I first removed the pannel holding the lp detector in place then found that the wires are to shore to take the acess pannel off witch is also the winterize access pannel I then made longer wires and conected then made sure that the lp detector worked properly			

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$51.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$51.00
Notes				

Submitted	Labor Amt	\$297.50	Approved	Labor Amt	\$297.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$297.50		Total	\$297.50

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.