



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75412
Promised Date:
24 DEC 24

CUSTOMER WORK ORDER

WO #: 75412

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 1219 BH TO CLOSE

Stock #: 11511
Stock Desc: 2025 TT COACHMEN
CATALINA 243RBSLE
Chassis #: 5ZT2CANB8SN300860
Serial #: 5ZT2CANB8SN300860
Mileage: 0
Licence:

Invoice #:
Date In: 13 NOV 24
Promised: 31 DEC 24
Date Sched:
Completed: 20 DEC 24
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

COMPLAINT: OUTSIDE KITCHEN DOOR IS BENT

CAUSE: OUTSIDE KITCHEN DOOR IS BENT

CORRECTION: OUTSIDE KITCHEN DOOR IS BENT

OUTSIDE KITCHEN DOOR IS BENT

The front corner of the door frame is bent, and the trim at that corner is bowed out. Flatten the trim back down to align with the other corners.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED

CAUSE: ENTRY DOOR NEEDS ADJUSTED



Customer #: 1000
BASDEN'S AMERICAN RV,





CORRECTION: Entry door steps are not install back far enough to allow entry door to close and latch. Folded steps up and removed mounting screws. Used spacer and relocated steps away from entry door to allow door to close and latch. Remounted steps with original mounting screws. Checked door closing with steps out and folded up in travel position. Door closes ok in both positions.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	59.50

Subtotal for Job #2: 59.50

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*75605 on 02 DEC 24

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CORRECTION: WINTERIZED UNIT AND DRAINED TANKS. USED 2 GAL OF ANTIFREEZE.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #WINTER* - Internal

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DKM	N/C
Z990	WINTERIZE UNIT	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER*: 0.00

Job #3 - Warranty

COMPLAINT: THE CURB SIDE FRONT CLOSET ROD IS TOO SHORT

CAUSE: THE CURBSIDE FRONT CLOSET ROD IS TOO SHORT

CORRECTION: 12/17/2024: Received replacement closet rod. Need to cut off to fit closet width. Cut new closet rod to fit.

Labor



W/O: 75412
Promised Date: 31 DEC 24



Customer #: 1000
BASDENS AMERICAN RV,



Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	34.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00

Parts

Part #	Description	Qty	Price	Total
6060641	ADJUSTABLE CLOSET ROD	1.00	22.99	22.99
Subtotal for Job #3:				56.99

Job #4 - Warranty

COMPLAINT: THE SHOWER DRAIN LEAKS

CAUSE: SHOWER DRAIN LEAKS

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	493.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	85.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	272.00

Parts

Part #	Description	Qty	Price	Total
111200	Fitting - ABS - Adapter - 1 1/2" - S	1.00	2.40	2.40
500627	CLEAR SIKASIL PLUS	1.00	18.23	18.23
89-8002	COUPLING 1 1/2" H X H	2.00	1.10	2.20
Subtotal for Job #4:				872.83

Parts Total: 45.82
Labour Total: 943.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 989.32

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 20 Dec 2024

