

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 75454  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725

Phone:

Stock Number: 11492 - 2025 APEX NANO 208BHS 5ZT2CXKB6SL017912  
VIN: 5ZT2CXKB6SL017912 HIN: SER#: 5ZT2CXKB6SL017912  
Mileage: 0 Work Order Comp: 27 JAN 25  
Auth. No: Dealer #:  
Warr. Date: Work Order Date: 16 NOV 24 Inv #: 413463

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
75454	2	THERE IS A HOLE IN THE FILLER AROUND THE REAR SKY LIGHT SEALED UP HOLES IN SEALER ON BATHROOM SKYLIGHT.	
75454	3	THE BALL COUPLER WILL NOT LATCH ALL THE WAY DOWN TO THE LOCKED POSITION Coupler is difficult to latch Received the new coupler and checked for damage. Pulled off the lp tank cover. Disconnected the lp lines from the lp tanks then unbolted the lp tanks and set to the side. Moved the 7way plug out of the way. Raised the camper up and set on jack stands and unbolted the tongue jack. Got a grinder and cut thru the welds of the factory coupler, then peeled off the coupler. Cleaned up the frame by grinding away the welds. Set the new coupler in place and put a weld tac from the frame to the coupler. After checking the coupler for alignment then welded the coupler to the frame. After the coupler had cooled down sprayed a light coat of black paint on the coupler and applied 2 more coats after that. After the paint was dry, bolted the jack to the coupler. Set the lp tanks back on the tongue and connected the lp lines and bolted down the tanks. Set the lp tank cover back on. Checked the latch on the coupler to make sure it still functions as it should.	
75454	4	THE FRONT BURNER ON THE STOVE WILL NOT STAY LIT.	
75454	1	THE FRONT DOCKING LIGHTS WILL NOT SHUT OFF. I FOUND THAT THE DOCKING LIGHT ON THE FRONT CAP WOULD NOT TURN	

