

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 2162553 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CXKB6SL017912 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 224 / 224 ITEM # AAPT208BHS DEALER RO # 75454 CLAIM START DATE 01/03/2025 CLAIM END DATE 01/01/1900
Labor rate: \$170.00 OWNER INFORMATION	

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 40-106-24-11-001253	Operational Description Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical
	Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2025-01-03 08:45:13 :: THE FRONT DOCKING LIGHTS WILL NOT SHUT OFF. I FOUND THAT THE DOCKING LIGHT ON THE FRONT CAP WOULD NOT TURN OFF WITH THE SWITCH. I REMOVED THE SWITCH AND FOUND THAT WIRING WAS JUMPING OVER THE DIVIDER MAKING CONTACT BETWEEN THE 2 PINS OF THE SWITCH. I FLIPPED THE CONNECTORS SO THAT THE WIRES WOULD FACE OUT AWAY FROM EACH OTHER. NOW THE LIGHTS TURN ON AND OFF AS THEY SHOULD.
	Model#	Dlr Sub Hrs 0.35 Sub Labor Amt \$59.50
	Serial#	Appr Hrs 0.30 Appr Labor Amt \$51.00
	Notes	

Labor

Line# 2	Operation Code 20-44-24-00-000544	Operational Description Rubber Roof - Exterior/Roof/Repair/No Tread Code
	Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2025-01-03 08:45:43 :: THERE IS A HOLE IN THE FILLER AROUND THE REAR SKY LIGHT SEALED UP HOLES IN SEALER ON BATHROOM SKYLIGHT.
	Model#	Dlr Sub Hrs 0.20 Sub Labor Amt \$34.00
	Serial#	Appr Hrs 0.20 Appr Labor Amt \$34.00
	Notes	

Labor

Line# 3	Operation Code 10-6-01-21-000106	Operational Description Coupler - Frame & Chassis/A-Frame, Tongue Jack & Coupler Assembly/Replace/Trailer Hitch
	Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2025-01-03 08:46:58 :: THE BALL COUPLER WILL NOT LATCH ALL THE WAY DOWN TO THE LOCKED POSITION IT WILL NOT LATCH AND NEEDS TO BE REPLACED
	Model#	Dlr Sub Hrs 0.80 Sub Labor Amt \$136.00
	Serial#	Appr Hrs 1.00 Appr Labor Amt \$170.00
	Notes	need a pic of the frame ID tag on the I-beam on the right front corner of the frame rail PHOTO ADDED sent to vendor for consideration I will authorize a new complete coupler, 1hr labor. VCB back under case #5548277

Thank you,

Paul W.
Lippert Customer Care Center Representative
p: 432.LIPPERT | f: 574.534.7161
e: customerservice@lci1.com

thank you

Labor
Line# 4

Operation Code
70-223-01-11-002736

Operational Description
Range Oven - complete - Appliances/Range, Oven (Furrion/Greystone)/Replace/
Electrical

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-01-03 08:47:54 :: THE FRONT BURNER ON THE STOVE
WILL NOT STAY LIT. NEED TO REPLACE THE LEFT CONTROL VALVE AND TEST TO MAKE SURE IT WORKS

Model# GGH12D2MA1B-BL

Dir Sub Hrs 0.70

Sub Labor Amt \$119.00

Serial# 10001690979122300449

Appr Hrs 0.70

Appr Labor Amt \$119.00

Notes

Submitted

Labor Amt \$348.50
Parts & Freight \$0.00
Total \$348.50

Approved

Labor Amt \$374.00
Parts & Freight \$0.00
Total \$374.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.