

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

Labor rate: \$170.00

OWNER INFORMATION

Retail Date of Purchase

CLAIM STATUS Authorized
CLAIM 2156084
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2CXHB7SS048163
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 220 / 220A
ITEM # APTT188RBST
DEALER RO # 75455
CLAIM START DATE 12/20/2024
CLAIM END DATE 01/01/1900

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
60-136-15-00-001499 Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-12-20 13:12:08 :: NO FLOW FROM THE FRESH TNAK TO WATER PUMP Removed underbelly cover and jackstand to follow waterline from tank to pump where I found a line kinked off where a 90 angle should have been. Cut line and installed a 90 angle and installed about 2 ft of plex line to replace kinked area.
Model# Dlr Sub Hrs 0.80 Sub Labor Amt \$136.00
Serial# Appr Hrs 0.80 Appr Labor Amt \$136.00
Notes

Labor

Line# 2 Operation Code Operational Description
30-102-01-00-001096 Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-12-20 13:12:47 :: THE INSERT TRIM ON THE SLIDE ROOM NEED TO BE CHANGED Trim on exterior of slideroom shrank. Pulled short trim and replaced it. Additional Note : bhoffman@americanrvcenter.com, 2024-12-20 13:15:22 :: cant find the right one
Model# Dlr Sub Hrs 0.30 Sub Labor Amt \$51.00
Serial# Appr Hrs 0.20 Appr Labor Amt \$34.00
Notes
insert only

Submitted Labor Amt \$187.00
Parts & Freight \$0.00
Total \$187.00

Approved Labor Amt \$170.00
Parts & Freight \$0.00
Total \$170.00

DEALER DATE
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER DATE
SIGNATURE

All repairs described have been inspected and are satisfactory.