

BASDEN RV CENTER, INC dba AMERICAN RV  
 600 E. Baseline Rd.  
 Evansville, IN  
 US  
 47725  
 812-867-5200

WARRANTY CLAIM # 75571  
 MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC  
 Customer: 54455 - MARY L. EBLEN  
 Address: 7208 HWY 60 E HENDERSON, KY

42420

Phone: 270-577-3404

Stock Number: 11287 - 2024 DELTA 262RB 7M5TD2922RC302222

VIN: 7M5TD2922RC302222 HIN: SER#: 7M5TD2922RC302222

Mileage: 0 Work Order Comp: 30 NOV 24

Auth. No: Dealer #:

Warr. Date: 27 FEB 24 Work Order Date: 29 NOV 24 Inv #: 412450

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
75571	1	CUSTOMER WAS WINTERIZING TRAILER AND FOUND THAT HE PUT THE HOSE IN THE FIRST OUTDOOR QUICK CONNECT TO PULL ANTIFREEZE. THAT WORKED, BUT WHEN HE WENT TO THE NEXT ONE AND TURNED THE FAUCET BACK ON, WATER STARTED POURING OUT OF THE FIRST QUICK CONNECT. CUSTOMER HAS BEEN UNABLE TO FINISH WINTERIZATION. spray port not stop running i first saw that the check valve intode of the spray port was not closing and had no spring i then removed d got with parts to get a new hose and a new spray port i then put new spray port into place and made sure to run antifreeze throught the new spray port	
75571	2	CUSTOMER ADVISES THAT THE QUICK CONNECT HOSE CAME APART WHEN CUSTOMER WENT TO HOOK IT TO THE TRAILER. hose broken i removed hose from unit and tagged with spray port under warenty shelf	

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
24404	1	Spray Port - O/S w/Metal MPT Conn		1.00	11.99	11.99
24405	2	COIL HOSE 15' - SPRAY DOCK - BLAC		1.00	11.99	11.99

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00

Claim : 75571

\*\*\*\*\*  
Lab Code Job# Description LABOUR Hrs Rate Total  
\*\*\*\*\*  
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00

Parts Total: 23.98  
Labour Total: 68.00  
Sublet Total: 0.00  
Extras Total: 0.00

>>>> Claim Total: 91.98

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_