



# Warranty Authorization Form

Date: 12/4/2024

Basden RV Center, Inc. DBA/ American RV  
600 E Baseline Rd  
Evansville, IN 47725  
Ph. (812) 867-5200  
cbruce@americanrvcenter.com

### General Information

Pre-Auth #: 80200 Unit: 7M5TD2922RC302222  
Series: Delta Model: 2024DEL262RB  
Notes:  
Status: Approved with Modifications

### Dealer Information

American RV  
(812) 867-5200  
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV  
600 E Baseline Rd  
Evansville, IN 47725

Requestor: Ben Hoffman  
Return Fax #:  
Email: bhoffman@americanrvcenter.com

### Operation Line 1

Flat Rate Code: 20038 SPRAY PORT - REPLACE (part return in Fault Code: VENDOR US)

Serial #: Model #: Notes:

Problem: CUSTOMER WAS WINTERIZING TRAILER AND FOUND THAT HE PUT THE HOSE IN THE FIRST OUTDOOR QUICK CONNECT TO PULL ANTIFREEZE. THAT WORKED, BUT WHEN HE WENT TO THE NEXT ONE AND TURNED THE FAUCET BACK ON, WATER STARTED POURING OUT OF THE FIRST QUICK CONNECT. CUSTOMER HAS BEEN UNABLE TO FINISH WINTERIZATION.

Time Requested: .4  
Time Allowed: .2  
Sublet Repairs: 0.00

Cause: spray port not stop running

Remedy: i first saw that the check valve intode of the spray port was not closing and had no spring i then removed d got with parts to get a new hose and a new spray port i then put new spray port into place and made sure to run antifreeze throught the new spray port

Part Return Req: Yes

Status: Approved with Modifications

### Operation Line 2

Flat Rate Code: 20038 SPRAY PORT - REPLACE (part return in Fault Code: VENDOR US)

Serial #: Model #: Notes:

Problem: CUSTOMER ADVISES THAT THE QUICK CONNECT HOSE CAME APART WHEN CUSTOMER WENT TO HOOK IT TO THE TRAILER.

Time Requested: .2  
Time Allowed: .2  
Sublet Repairs: 0.00

Cause: hose broken

Remedy: i removed hose from unit and tagged with spray port under warenty shelf

Part Return Req: Yes

Status: Approved