



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79286



Customer #: 10558
WAHL, JR., RICHARD L.



CUSTOMER WORK ORDER

WO #: 79286

Customer: 10558 - WAHL, JR. ,
RICHARD L. - 812-431-2114

Tag:

Author: GA

Location: WAITING ON FIBERNEW

INVOICE

Stock #: 11651

Stock Desc: 2026 TT ALLIANCE RV

DELTA 281BH

Chassis #: 7M5TD3126TC307285

Serial #: 7M5TD3126TC307285

Mileage: 0

Licence:

Invoice #:

Date In: 18 MAR 26

Promised:

Date Sched:

Completed: 10 APR 26

Warr. Date: 28 FEB 26

Job #1 - Warranty

COMPLAINT: SCRATCH ON TRIM IN SLIDE ROOM ABOVE RECLYNER ON TOP LEFT SIDE WHEN
STANDING IN FRONT OF RECLYNER

CORRECTION: Retrieved unit and hooked up Shore power. Compartment was locked with disconnect...
pulled door cylinder and retrieved Key for Compartment and turned disconnect ON. Took pics and
submitted part request for Facia Board with chips in it. Turned disconnect back off, disconnect Shore power
and put back into storage.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	79.95
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	11.70
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	25.35

Parts

Part #	Description	Qty	Price	Total
33854	Fascia - 5.50 x 144 - Salinas Oak	1.00	17.10	17.10

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-FASCIA	1.00	203.91	203.91

Subtotal for Job #1: 338.01

Job #2 - Internal

NON DOOR SIDE STORAGE DOOR ON SLIDE ROOM HAS GLUE FROM A STICKER ON IT. SEE
GREG A WITH QUESTIONS

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: WHEN CUSTOMER RAN THE SLIDE ROOM OUT IT TORE A SPOT IN THE FLOOR

CORRECTION: Found and took pics of cut on vynle floor.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00



Sublet	
Description	Total
LINO REPAIR	425.00

Subtotal for Job #3: 425.00

Job #4 - Warranty

COMPLAINT: MAGNET AND SCREW HAS COME OFF OF THE BOTTOM DRAWER

CAUSE: Remount Magnet for internal drawer.

CORRECTION: Located the drawer customer was talking about after hunting thru the unit... turned out the drawer was Located inside and behind Cabinet Doors under TV. Remounted Magnetic catch.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	19.50

Subtotal for Job #4: 19.50

Job #5 - Warranty

COMPLAINT: SCREEN IN DOOR BY BUNK HAS HOLE IN THE SCREEN

CAUSE: Damaged screen

CORRECTION: Took pics, measured and cut new piece of screen. Removed old screening from damaged section of door. One single insert that holds the screening in is installed on whole door including top and bottom section... i had to center the new screening and work from the top middle down each side which was difficult to keep screen tight while keeping slack out of insert while also forcing insert into track but i managed and cut extra off.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	156.00

Subtotal for Job #5: 156.00

Job #6 - Warranty

COMPLAINT: TABLE HAS CHIP IN THE CORNER.

CORRECTION: Took pics and measurements, 29in x 32in x 1in and submitted part request.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	58.50
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Parts				
Part #	Description	Qty	Price	Total
ALL34990	TOP - Dinette - 29 x 32 w/Grooves -	1.00	150.66	150.66

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-TABLE TOP	1.00	29.47	29.47

Subtotal for Job #6: 238.63

Job #7 - Internal

COMPLAINT: BOTTOM LIGHT ON FRONT OF CAMPER WAS LOOSE. CUSTOMER WANTS TO MAKE SURE THE TOP LIGHT IS STUCK ON PROPERLY

CAUSE: .

CORRECTION: Lights are secured.

Labor



Customer #: 10558
WAHL, JR., RICHARD L.



Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #7:	0.00
----------------------	------

Job #8 - Warranty

COMPLAINT: BLIND BEHIND RIGHT SIDE OF COUCH IS CROOKED

CAUSE: Blind mount brackets were pulled from their mounted positions

CORRECTION: The lock mounted brackets that secures blinds in place was onky being held up by the center mount... both of the end mounts were pulled from the blind covers where they mount. Had to drop the blind and unclip the brackets off of blind and reinstall them and reinstall blind.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	19.50

Subtotal for Job #8:	19.50
----------------------	-------

Parts Total:	167.76
Labour Total:	370.50
Sublet Total:	425.00
Extras Total:	233.38
WORK ORDER TOTAL:	1,196.64

Thank you for being a valued customer. We appreciate your business.
All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature _____

Date: 10 Apr 2026

W/O: 79286



Customer #: 10558
 WAHL, JR., RICHARD L.

