



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78792



Customer #: 54323
KASTLE, WILLIAM E.



CUSTOMER WORK ORDER

WO #: 78792 (Appointment Date: 06 JAN 2026 - Time: 09:30am)

Customer: 54323 - KASTLE, WILLIAM E. Stock #:
- Stock Desc: 2024 C FOREST RIVER
Tag: FREELANDER
Author: GA Chassis #:
Location: 0120 CHECK WORK Serial #: 1FDXE4FN9RDD11728
Mileage: 6481
Licence:

Invoice #: 425829
Date In: 06 JAN 26
Promised:
Date Sched:
Completed: 12 JAN 26
Warr. Date:

Job #1 - Warranty

COMPLAINT: THE FURNACE FAN WILL RUN, BUT IT WILL NOT IGNITE. CUSTOMER ADVISES THAT HE IS GETTING 1 RED FLASH AT THE INDICATOR ON THE FURNACE.

CAUSE: Sail switch

CORRECTION: Went to the thermostat turned the furnace on and waited for it to fire. The furniture never fired and then the red led light threw a one flash code which leads to air flow. Unplug the cell switch and put a 5 AM use and place. And then the Unplug the sail switch and put a 5amp fuse in place and then the furnace had fired. Took pictures and put in a part's request for a new sail switch.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	185.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Other Services

Code	Description	Qty	Price	Total
PARTS	SALE SWITCH 30% MARK UP	1.00	7.47	7.47

Subtotal for Job #1: 192.47

Job #WINTER - External

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterizing 2 gallons

CORRECTION: Turned the valves at the water heater and city water connection. Connected a hose then added 2 gallons through the kitchen faucet, bathroom faucet, toilet, shower and outside shower. Drained the low pions. Drained the black, grey and fresh tanks.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	SAR	N/C
Z990	WINTERIZE UNIT	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #3 - Warranty

COMPLAINT: OVERHEAD A/C UNIT IN BEDROOM ISN'T WORKING

CAUSE: The ac compressor not working but the fan works.

CORRECTION: Plugged the shore power , then opened the slide room in the bedroom to turn the ac on. The ac turned on and I let it cool for fifteen minutes while checking the temperature for the intake and exhaust. Got the dometic paperwork. Took off the ac cover on the roof and took a fan of draw and compressor and draw and then filled out the paperwork took pictures. Turned off the ac.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	138.75
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Other Services

Code	Description	Qty	Price	Total
PARTS	ADB 30% COST	1.00	41.56	41.56

Subtotal for Job #3: 180.31

Job #4 - External

LOW DRAIN POINT IS IN LEFT REAR COMPARTMENT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #4: 0.00

Job #5 - External

COMPLAINT: CHECK PSI IN TIRES

CAUSE: Low tire pressure

CORRECTION: Pull off the hubcaps then check and set tire pressure. Each tire was between 2 and 10 psi difference from factory psi. Set each tire accordingly to the sticker and the driver door. Put the hub caps back on.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #5: 0.00

Parts Total: 0.00
Labour Total: 323.75
Sublet Total: 0.00
Extras Total: 49.03
WORK ORDER TOTAL: 372.78