



Alix Mongiat <alix@dealer-advisors.com>

Pre-Auth # 931371

John Hamilton <jhamilton@granddesignrv.com>
To: Alix Mongiat <alix@dealer-advisors.com>

Mon, Mar 23, 2026 at 4:38 PM

Good Afternoon,

Response from vendor:

Thank you for the response. We advised the technician that there is a voltage concern, as the voltage was dropping significantly during operation. This voltage issue will need to be addressed, or the fuses will likely continue to blow.

Thank you,

Teesha G.
Lippert Customer Care Representative
432-Lippert

What they are saying is they did not tell the tech to change the size of the fuse or the size of the wire.

We must stand by our decision, to deny the request to modify the electrical system.

[Quoted text hidden]