

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11383

Date In:	08 OCT 24	Author:	KOTT
Promised Date:	04 JUL 25	Stock No:	11253
:	:	Year:	2025
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	PUMA TT
:	WISCONSIN RAPIDS, WI	Model:	32BHQ5
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4TPUH28SP103645	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
NTTS    COMPLAINT:  NEW TRAVEL TRAILER STOCK PREP                I      PDI      PRE-D
        CAUSE:      Done
        CORRECTION: Done
WARR    COMPLAINT:  WARRANTY REPAIR 1 - All the decals on        W      1021    FORES
        the front cap are peeling.
        CAUSE:      1000 DEFECT FROM MANUFACTURER. Every
        decal on the front cap is peeling and
        needs to be replaced.
        CORRECTION: ... REQUEST 3 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 2 - There is a crack        W      1021    FORES
        around the ods storage lock.
        CAUSE:      1000 DEFECT FROM MANUFACTURER. We will
        have to order a new door and one blue
        stripe decal.
        CORRECTION: ... REQUEST 1.5 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 3 - There is a white        W      1021    FORES
        residue on the ods T-molding.
        CAUSE:      1000 DEFECT FROM MANUFACTURER. I cleaned
        it off with quick-solve and a rag.
        CORRECTION: Done. REQUEST .20 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 4 - The ds tire skirting W      1021    FORES
        is cracked.
        CAUSE:      1000 DEFECT FROM MANUFACTURER. We will
        need a new tire skirting. 68 x 11 1/4
        CORRECTION: ... REQUEST 2.5 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 5 - There is a brown        W      1021    FORES
        residue on the main floor in multiple
        areas.
```

Continued on page 2

Work Order : 11383

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
      CAUSE:      1000 DEFECT FROM MANUFACTURER. I cleaned
                  it off with quick-solve and a rag. I
                  found a few brown spots on the bottom of
                  the slide floor that I cleaned off as
                  well.
WARR      CORRECTION: Done. REQUEST .40 HOURS OF LABOR
      COMPLAINT: WARRANTY REPAIR 6 - The baton strip      W      1021      FORES
                  above the bunkroom door is cracked.
      CAUSE:      1000 DEFECT FROM MANUFACTURER. I covered
                  the crack in putty.
WARR      CORRECTION: Done. REQUEST .10 HOURS OF LABOR
      COMPLAINT: WARRANTY REPAIR 7 - There is a brown      W      1021      FORES
                  residue on the bottom of the couch style
                  in the bunkroom.
      CAUSE:      1000 DEFECT FROM MANUFACTURER. I cleaned
                  it off with quick-solve and a rag.
WARR      CORRECTION: Done. REQUEST .10 HOURS OF LABOR
      COMPLAINT: WARRANTY REPAIR 8 - The corner molding      W      1021      FORES
                  in the bunk room is cracked.
      CAUSE:      1000 DEFECT FROM MANUFACTURER. I
                  covered it up with putty.
WARR      CORRECTION: Done. REQEUST .20 HOURS OF LABOR
      COMPLAINT: WARRANTY REPAIR 9 - The two overhead      W      1021      FORES
                  cabinets by the kitchen sink are
                  cracked.
      CAUSE:      1000 DEFECT FROM MANUFACTURER I was
                  able to cover up the cracks on the left
                  cabinet door but the cracks on the right
                  cabinet door are too big to hide. We
                  will have to replace the right cabinet
                  door.
WARR      CORRECTION: ...
      COMPLAINT: WARRANTY REPAIR 10 - The plastic seam      W      1021      FORES
                  molding is bunched up in the bunkroom
                  corners.
      CAUSE:      1000 DEFECT FROM MANUFACTURER. I trimmed
                  the molding and glued it down flat.
WARR      CORRECTION: Done. REQUEST .20 HOURS OF LABOR
      COMPLAINT: WARRANTY REPAIR 11 - The cabinet door in W      1021      FORES
                  both bathrooms are cracked.
      CAUSE:      1000 DEFECT FROM MANUFACTURER. I was
                  able to cover both of the cracks in the
                  doors with putty.
WARR      CORRECTION: Done. REQUEST .20 HOURS OF LABOR
      COMPLAINT: WARRANTY REPAIR 12 - The syle is ripped W      1021      FORES
                  in the cabinet below the bunk beds.
      CAUSE:      1000 DEFECT FROM MANUFACTURER. I covered
                  it up with putty.
      CORRECTION: Done REQUEST .20 HOURS OF LABOR

```

Continued on page 3

Work Order : 11383

WARR	COMPLAINT:	WARRANTY REPAIR 13 - There is a baton strip that is cut too short in the rear bathroom.	W	1021	FORES
	CAUSE:	1000 DEFECT FROM MANUFACTURER. I covered it up with putty.			
	CORRECTION:	Done. REQUEST .10 HOURS OF LABO R			
WARR	COMPLAINT:	WARRANTY REPAIR 14 - The door knob in the bedroom hits the USB charger.	W	1021	FORES
	CAUSE:	1000 DEFECT FROM MANUFACTURER. No repair at this time just noting if it becomes an issue.			
	CORRECTION:	Done. NOTING			
WARR	COMPLAINT:	WARRANTY REPAIR 15 - The a/c rattles.	W	1021	FORES
	CAUSE:	1000 DEFECT FROM MANUFACTURER. A piece of aluminum tape came loose and was touching the blower wheel. I ripped it off and put a new piece on.			
	CORRECTION:	Done. REQUEST .30 HOURS OF LABOR			
WARR	COMPLAINT:	WARRANTY REPAIR 16 - There is a hole in the dicor along the front vent.	W	1021	FORES
	CAUSE:	1000 DEFECT FROM MANUFACTURER. I cleaned the area and sealed over the hole.			
	CORRECTION:	Done REQUEST .10 HOURS OF LABOR			
WARR	COMPLAINT:	WARRANTY REPAIR 17 - There is a large air bubble in the ods rear slide decal.	W	1021	FORES
	CAUSE:	1000 DEFECT FROM MANUFACTURER. We will have to order a new decal.			
	CORRECTION:	... REQUEST .50 HOURS OF LABOR			
WARR	COMPLAINT:	WARRANTY REPAIR 18 - There is a stain on the rear ods slide rug.	W	1021	FORES
	CAUSE:	1000 DEFECT FROM MANUFACTURER. The rug isn't stained. Some of the threads are fraying. No repair at this time. Just noting if it becomes an issue.			
	CORRECTION:	Done. REQUEST .20 HOURS OF LABOR			
WARR	COMPLAINT:	WARRANTY REPAIR 19 - There is a decal that is peeling behind the ods rear slide.	W	1021	FORES
	CAUSE:	1000 DEFECT FROM MANUFACTURER. I cleaned the area and went over the edge with silicone to hold the decal down.			
	CORRECTION:	Done. REQUEST .20 HOURS OF LABOR			
WARR	COMPLAINT:	WARRANTY REPAIR 20 - There is a water leak around the fresh drain.	W	1021	FORES
	CAUSE:	NPF. When I was done with the prep I pulled the unit outside and when I went to drain the tanks I noticed water dripping out of the back side of the fresh drain. I drained the tank, partially dropped the underbelly and the underbelly is damp around the drain. I can't see any leaks so I started filling			

Continued on page 4

Work Order : 11383

the fresh tank again and i still don't see any leaks. I moved the unit with lift trying to duplicate when I first noticed the leak and no leaks can be found. Its possible it was just water that collected in the underbelly from being on the lot and thats where it just drained out.

CORRECTION: Done. REQUEST .50 HOURS OF LABOR

```
*****
Job#  Lab Code  Description    LABOUR    Mech Bill to      Hrs      Rate      Total
*****
NTTS  RV1F-1A   NEW STOCK PREP          JGK  I-PDI          0.25     70.00     17.50
NTTS  RV1F-1A   NEW STOCK PREP          JGK  I-PDI          1.13     70.00     79.10
NTTS  RV1F-1A   NEW STOCK PREP          JGK  I-PDI          2.75     70.00    192.50
ARR01  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR02  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR03  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR04  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.45    140.00     63.00
ARR05  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR06  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.49    140.00     68.60
ARR07  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR08  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR09  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.42    140.00     58.80
ARR10  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR11  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR12  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR13  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR14  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR15  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR16  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR01  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR02  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR03  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR04  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR05  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR06  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.01    140.00      1.40
ARR07  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR08  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR09  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR10  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR11  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR12  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR13  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR14  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR15  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR16  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR18  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
ARR04  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.05    140.00      7.00
ARR18  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.00    140.00      0.00
ARR17  Z992      MISC LABOUR CODE (WARR JGK  W-1021        0.50    140.00     70.00
*****
```

Continued on page 5

Work Order : 11383

```

*****
Job#  Lab Code  Description   LABOUR   Mech Bill to      Hrs      Rate      Total
*****
ARR17 Z992      MISC LABOUR CODE (WARR JGK  W-1021      0.00     140.00      0.00
ARR09 Z992      MISC LABOUR CODE (WARR JGK  W-1021      0.08     140.00     11.20
ARR19 Z992      MISC LABOUR CODE (WARR JGK  W-1021      0.50     140.00     70.00
ARR19 Z992      MISC LABOUR CODE (WARR JGK  W-1021      0.00     140.00      0.00
ARR19 Z992      MISC LABOUR CODE (WARR JGK  W-1021      0.00     140.00      0.00
NTTS RV1F-1A    NEW STOCK PREP      JGK  I-PDI      0.37      70.00     25.90
ARR20 Z992      MISC LABOUR CODE (WARR JGK  W-1021      0.50     140.00     70.00

```

```

*****
Job #  Excode    Description   EXTRAS      bill to      Qty      Price      Total
*****
ARR01  SSE        SHOP SUPPLIES - EXTERNAL  W-1021      1.00      0.00      0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      PDI          0.00      315.00      0.00      0.00      0.00      315.00
W      1021          0.00     1400.00      0.00      0.00      0.00     1,400.00

Totals          0.00     1715.00      0.00      0.00      0.00     1,715.00

```

&k2S
&k0S