

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12395

Date In: 18 JUL 25 Author: MGRAY
Promised Date: 31 MAY 26 Stock No: 11258
: Year: 2025
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: PUMA DESTINATION
: CHICAGO, IL Model: 402LFT
Postal/Zip: 60673-1218 Miles/Hrs: 0
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: WS COMP
Purchased Date: 17 JAN 25 :
Delivery Date: 25 APR 25 :
InService Date: :
Serial#: 4X4TPUS2XSP104353 :

Job # Description JOB INFORMATION Type Bill To

SS SEASONAL STORAGE E 17595 BIRSC
WS COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF E 17595 BIRSC
CONTAINED - TOWABLE
CAUSE: Unit needed to be winterized
CORRECTION: Unit winterized
PD COMPLAINT: PICK UP AND DELIVERY WITHIN 15mi E 17595 BIRSC
(CAMALOT, SHERWOOD, ARROWHEAD) 1023
CARDIFF CT ROME
CAUSE: Unit needed to be picked up 10/15
1 COMPLAINT: CUSTOMER STATES THAT THERE IS SOMETHING W 1021 FORES
WRONG WITH THE SLIDING PATIO DOOR- WOULD
LIKE TO HAVE LOOKED AT- PER CMR IT DOES
NOT OPEN OR CLOSE PROPERLY-
CAUSE: pics and measurements taken the slide
patio door framework is bent due to
installation and will have to look at
the header above the patio door as well
to make sure that its straight after
removal of patio door framework
CORRECTION: will need a complete patio door with
framework measurements taken couldn't
find a tag with measurements.....
request: 3.0 ** need assistance with
parts, only finding 60"x72" need
60"x74**
2 COMPLAINT: PER CMR- THE TANKLESS HOT WATER HEATER W 1021 FORES
DOES NOT OPERATE CORRECTLY- CUSTOMER
STATES THAT WHEN HE TAKES A SHOWER THE

Continued on page 2

Work Order : 12395

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
HOT WATER WILL WORK FOR A COUPLE OF
MINUTES THEN IT WILL GO COLD- THE
CUSTOMER HAS TRIED TURNING OFF THE COLD
WATER BUT THE WATER IN THE SHOWER STAYS
COLD- WOULD LIKE TO HAVE DIAGNSOED-
CAUSE:  after doing flow testing on shower where
        getting water restrictions through
        showers faucets and shower head we
        getting about 3/4 gallon a minute i
        checked flow valve on water heater is
        full flow and all othet faucets are
        working about gallon to gallon and half
        minute so the shower faucet and shower
        head is restricted to much causes the
        water temp to hi and limit out water
        heater
CORRECTION: will need a new shower faucet and shower
            head for a tankless water heater.....
            request: 3.0 hr (diag: 2.4 R&R of
            faucet and shower head: .6 ) **Need
            assistance finding correct parts. ***

```

```

*****
Job # Part No   Description           PARTS   Bill to   Qty   Price   Total
*****
WS    071247312003 -50 ANTIFREEZE/ 1 GALLON E-17595   0     9.62    0.00
*****

```

```

*****
Job#  Lab Code  Description           LABOUR   Mech Bill to   Hrs   Rate   Total
*****
WS W495      WINTERIZE RV (WATER SY JT   E-17595   0.70   130.00   91.00
PD Z990      PICK UP CAMPER WITHIN   JT   E-17595   1.13   130.00   146.90
PD Z990      DELIVER CAMPER WITHIN   JT   E-17595   1.12   130.00   145.60
1 Z992      MISC LABOUR CODE (WARR JS   W-1021   0.50   140.00   70.00
2 Z992      MISC LABOUR CODE (WARR JS   W-1021   0.00   140.00   0.00
2 Z992      MISC LABOUR CODE (WARR JS   W-1021   0.50   140.00   70.00
2 W150      FAUCET, R & R           W-1021   0.00   140.00   0.00
2 RV10-20   SHOWER HEAD R&R         W-1021   0.00   140.00   0.00
1 E745      DOOR, ENTRY , R & R     W-1021   0.00   140.00   0.00
*****

```

```

*****
Job #  Excode   Description           EXTRAS   bill to   Qty   Price   Total
*****
SS SS      SEASONAL STORAGE           E-17595   0.00   0.00    0.00
SS SSE     SHOP SUPPLIES - EXTERNAL   E-17595   1.00   28.76   28.76
SS J-ADJ   QUOTE ADJUSTMENT           E-17595   1.00   178.24  178.24
WS J-ADJ   QUOTE ADJUSTMENT           E-17595   1.00   14.00   14.00
PD J-ADJ   QUOTE ADJUSTMENT           E-17595   1.00   -34.50  -34.50
*****

```

Continued on page 3

Work Order : 12395

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	17595	0.00	383.50	0.00	186.50	31.38	601.38
W	1021	0.00	140.00	0.00	0.00	0.00	140.00
	Totals	0.00	523.50	0.00	186.50	31.38	741.38

&k2S
&k0S