

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11707C

Date In: 12 MAY 25 Author: DLUCAS
Promised Date: 31 DEC 25 Stock No: 11258
: Year: 2025
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: PUMA DESTINATION
: CHICAGO, IL Model: 402LFT
Postal/Zip: 60673-1218 Miles/Hrs: 0
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: DB5/22 - MAILED BILL
Purchased Date: 17 JAN 25 :
Delivery Date: 25 APR 25 :
InService Date: :
Serial#: 4X4TPUS2XSP104353 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 5 - THERE IS A LEAK W 1021 FORES
UNDER THE SINK WHEN USING THE "BAR
FAUCET" - CMR WILL SHOW YOU AT SITE.
CAUSE: pics taken what I diagnose is the veggie
sprayer is cracked allowing water to
drain into lower sink cabinet
CORRECTION: removed and install new veggie sprayer I
couldn't test due to water supply locked
up
SC SERVICE CALL: 1023 CARDIFF COURT- ROME E 17595 BIRSC
1 COMPLAINT: CUSTOMER STATES THAT ONE OF THE CLIPS ON W 1021 FORES
THE BATHROOM MIRROR IS BROKEN-
CAUSE: Will need plastic mirror clips pics
taken
CORRECTION: remove and install the new plastic clip
that holds mirror to wall
2 COMPLAINT: CUSTOMER STATES THAT THE STOPPER AT THE W 1021 FORES
BOTTOM OF THE SINK IN THE KITCHEN THAT
IS SUPPOSED TO HOLD WATER DOES NOT HOLD
ANY WATER-
CAUSE: the drainer stopper does work insert the
stopper in sink drain and then turn
stainless dial to left to lock into
place for tight seal. NEED .10 FOR
REPAIR.
CORRECTION: put strainer into place for kitchen sink
and then turn stainless dial to left to
lock in

Continued on page 2

Work Order : 11707C

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
3       COMPLAINT:  CUSTOMER STATES THAT THE SCREEN DOOR          W    1021   FORES
          DOES NOT GO INTO THE TRACK- IT IS BY THE
          KITCHEN SINK-
          CAUSE:      we need to get ahold mfg about these
                    screen door are not right corners of
                    screen door digging in metal I tried
                    adjusting the wheels seems like they
                    angled the wrong directions does not
                    work with patio frame is there a
                    different option screen door we can try
                    I've come across several like this they
                    don't work I've tried flipping screen
                    door still not right
          CORRECTION: still the same screen door design I
                    installed and adjustments done the best
                    I can to make it work
    
```

```

*****
Job # Part No  Description      PARTS      Bill to  Qty  Price  Total
*****
WARR0 822069730  SINK PART: BLACK SINK SPRA W-1021      1    17.16  17.16
1      822091598  CLIP, MIRROR CLEAR PLASTIC W-1021      1     0.07   0.07
3      822053515A SCREEN DOOR FOR PATIO DOOR W-1021      1    53.13  53.13
    
```

```

*****
Job# Lab Code Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR05 Z992      MISC LABOUR CODE (WARR JS W-1021  0.52 140.00 72.80
ARR05 WARR     MANUFACTURER WARRANTY JS W-1021  0.50 140.00 70.00
1 WARR     MANUFACTURER WARRANTY JS W-1021  0.50 140.00 70.00
1 WARR     MANUFACTURER WARRANTY JS W-1021  0.50 140.00 70.00
2 WARR     MANUFACTURER WARRANTY JS W-1021  0.25 140.00 35.00
3 WARR     MANUFACTURER WARRANTY JS W-1021  0.65 140.00 91.00
3 WARR     MANUFACTURER WARRANTY JS W-1021  0.10 140.00 14.00
    
```

```

*****
Job # Excode  Description  EXTRAS      bill to  Qty  Price  Total
*****
SC SSE      SHOP SUPPLIES - EXTERNAL E-17595  1.00  0.00   0.00
SC SC       SERVICE CALL           E-17595  15.00  3.75  56.25
SC SC       SERVICE CALL           E-17595  15.00  3.75  56.25
3 FRT       FREIGHT FOR DOOR, CLIP AND W-1021  1.00 161.04 161.04
    
```

```

*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
E  17595      0.00    0.00    0.00  112.50  6.22  118.72
W  1021      70.36   422.80    0.00  161.04  0.00  654.20
    
```

Continued on page 3

Work Order : 11707C

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	70.36	422.80	0.00	273.54	6.22	772.92

&k2S
&k0S