

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12767B

Date In:	01 APR 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	11476
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	403LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 4/1
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS29TP107018	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Sliderooms have bare W    1021    FORES
        wood exposed on slideroom walls
        CAUSE:      Mfg left bare wood  I NEED TO HAVE A
        PREAUTH APPROVED BEFORE I CAN REPAIR
        THESE PER MATT 4 SLIDEROOM ARMS NEED IT
        SO 8 HOURS ARE REQUESTED THANK YOU
        CORRECTION: .....
WARR    COMPLAINT:  WARRANTY REPAIR 2 - Dark wood has smears W    1021    FORES
        on it
        CAUSE:      Streaks and marks of white on the dark
        colored wood
        CORRECTION: I used quick solve to remove excess
        putty on the slide room arms  REQUEST:
        .4
WARR    COMPLAINT:  WARRANTY REPAIR 3 - DS sofa pull out bed W    1021    FORES
        legs are installed so tight that you can
        hardly get the legs to come down
        CAUSE:      Mfg of sofa really overtightened the
        nutts holding bolt so much so it dented
        in the frame
        CORRECTION: I loosened both nutts  REQUEST:.2
WARR    COMPLAINT:  WARRANTY REPAIR 4 - light lens off of 3  W    1021    FORES
        ceiling lights
        CAUSE:      Light lens fell off 1 is missing
        CORRECTION: I reinstalled 2 lens then installed one
        new lens  REQUESTed:.1
WARR    COMPLAINT:  WARRANTY REPAIR 5 - upper windows have    W    1021    FORES
        silicone smeared on them
```

Continued on page 2

Work Order : 12767B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      CAUSE:      Smearred silicone from mfg on windows
                  inside and out
      CORRECTION: I did the windows I could the lift ran
                  out so could not finish   REQUEST: .7
WARR    COMPLAINT: WARRANTY REPAIR 6 - Bathroom sink faucet W   1021   FORES
                  has 2 deep scratches in its finish
      CAUSE:      Scratch on faucet handle CAME THIS WAY
                  FROM MFG  PLEASE ORDER NEW FAUCET I CAN
                  NOT BUFF OR REMOVE VE THIS IT IS
                  SCRATCHED DEEP
      CORRECTION: ..... REQUEST: .5
WARR    COMPLAINT: WARRANTY REPAIR 7 - Shower pan has a few W   1021   FORES
                  black scratches in it
      CAUSE:      Scratches in shower pan
      CORRECTION: DONE  REQUEST: .2

```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty   Price   Total
*****
WARR0 822015386 LIGHT - FLUSH MOUNT, LED, W W-1021      1     1.99     1.99

```

```

*****
Job# Lab Code   Description           LABOUR   Mech Bill to   Hrs   Rate   Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.31  140.00   43.40
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.19  140.00   26.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50  140.00   70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00  140.00    0.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50  140.00   70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.48  140.00   67.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.02  140.00    2.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.17  140.00   23.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.33  140.00   46.20
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50  140.00   70.00
ARR06 W150      FAUCET, R & R           W-1021      0.00  140.00    0.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50  140.00   70.00

```

```

*****
Job # Excode   Description           EXTRAS           bill to   Qty   Price   Total
*****
ARR01 SSE      SHOP SUPPLIES - EXTERNAL W-1021      1.00    0.00    0.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id           Parts   Labour   Sublet   Extras   Tax   Total
*****
W      1021            1.99    490.00    0.00    0.00    0.00   491.99

```

Continued on page 3

Work Order : 12767B

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	1.99	490.00	0.00	0.00	0.00	491.99

&k2S
&k0S