

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12767B

Date In:	01 APR 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	11476
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	403LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 4/1
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS29TP107018	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - Sliderooms have bare wood exposed on slideroom walls	1021	FORES
	CAUSE:	Mfg left bare wood I NEED TO HAVE A PREAUTH APPROVED BEFORE I CAN REPAIR THESE PER MATT 4 SLIDEROOM ARMS NEED IT SO 8 HOURS ARE REQUESTED THANK YOU MANU DIDN'T FINISH COMPLETELY SEALING SLIDEOUT		
WARR	CORRECTION:	NEED TO SEAL THE BOARD REQUEST: 8HR		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - Dark wood has smears on it	1021	FORES
	CAUSE:	Streaks and marks of white on the dark colored wood		
	CORRECTION:	I used quick solve to remove excess putty on the slide room arms REQUEST: .4		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - DS sofa pull out bed legs are installed so tight that you can hardly get the legs to come down	1021	FORES
	CAUSE:	Mfg of sofa really overtightened the nutts holding bolt so much so it dented in the frame		
	CORRECTION:	I loosened both nutts REQUEST:.2		
WARR	COMPLAINT:	WARRANTY REPAIR 4 - light lens off of ceiling lights	1021	FORES
	CAUSE:	Light lens fell off 1 is missing		
	CORRECTION:	I reinstalled 2 lens then installed one new lens REQUESTED:.1		

Continued on page 2

Work Order : 12767B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 5 - upper windows have      W    1021    FORES
          silicone smeared on them
          CAUSE:      Smeared silicone from mfg on windows
                      inside and out
          CORRECTION: I did the windows I could the lift ran
                      out so could not finish    REQUEST: .7
WARR    COMPLAINT:  WARRANTY REPAIR 6 - Bathroom sink faucet W    1021    FORES
          has 2 deep scratches in its finish
          CAUSE:      Scratch on faucet handle CAME THIS WAY
                      FROM MFG  PLEASE ORDER NEW FAUCET I CAN
                      NOT BUFF OR REMOVE VE THIS IT IS
                      SCRATCHED DEEP
          CORRECTION: ..... REQUEST: .5
WARR    COMPLAINT:  WARRANTY REPAIR 7 - Shower pan has a few W    1021    FORES
          black scratches in it
          CAUSE:      Scratches in shower pan
          CORRECTION: DONE  REQUEST: .2

```

```

*****
Job # Part No  Description          PARTS          Bill to  Qty    Price    Total
*****
WARR0 822015386 LIGHT - FLUSH MOUNT, LED, W W-1021      1      1.99      1.99

```

```

*****
Job#  Lab Code  Description          LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.31   140.00   43.40
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.19   140.00   26.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50   140.00   70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.00   140.00    0.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50   140.00   70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.48   140.00   67.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.02   140.00    2.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.17   140.00   23.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.33   140.00   46.20
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50   140.00   70.00
ARR06 W150      FAUCET, R & R              W-1021      0.00   140.00    0.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021      0.50   140.00   70.00

```

```

*****
Job #  Excode    Description          EXTRAS          bill to    Qty    Price    Total
*****
ARR01  SSE       SHOP SUPPLIES - EXTERNAL  W-1021      1.00    0.00    0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id    Parts    Labour    Sublet    Extras    Tax    Total
*****
W    1021        1.99     490.00     0.00     0.00     0.00    491.99

```

Continued on page 3

Work Order : 12767B

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	1.99	490.00	0.00	0.00	0.00	491.99

&k2S
&k0S