

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12781B

Date In: 30 JAN 26 Author: MGRAY
Promised Date: 09 APR 26 Stock No: 11469
: Year: 2026
Customer Name: 14640 - FRITSCHLER, MA Manufacturer: FOREST RIVER
Address: 523 SYCAMORE STREET Brand: PUMA CAMPING EDITION
: SAUK CITY, WI Model: 305BHCE
Postal/Zip: 53583 Miles/Hrs: 0
Phone#(res): 608-963-0733 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: FRITSCH@CHARTER.NET Tag#: DB: 1/30
Purchased Date: 21 JUN 25 :
Delivery Date: 09 APR 26 :
InService Date: :
Serial#: 5ZT2PUWB4T4026004 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - on the left bench of W 1021 FORES
the dinette table the wood support for
the seat on the wall is rotten
CAUSE: The support on the bench along the wall
was rotten and broken, i took the old
wood out and replaced it with a 1x2 from
the wood room
CORRECTION: Done REQUEST: .4 APPROVED: .3
WARR COMPLAINT: WARRANTY REPAIR 2 - L.P tank is leaking W 1021 FORES
out the back
CAUSE: The back of the nozzle was leaking, i
replaced the tank with the same brand
from parts
CORRECTION: Done REQUEST: .6 APPROVE: .2
WARR COMPLAINT: WARRANTY REPAIR 3 - wall on the ods next W 1021 FORES
to the cabinets across from the bathroom
had wall paper poorly stuck to it,
peeled it off and found a gouge in the
wall that they tried to cover from
factory
CAUSE: There is a gouge in the wall panel on
the ods by the cabinets across from the
bathroom we have a spare piece of wall
panel in the same color from the bunk
that i tried to use to cover it but the
panel is to short, we will have to order
a new panel, hight-78 Width-17 3/4 We
will also need baton strips in same

Continued on page 2

Work Order : 12781B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                color one broke in the process of taking
                them off  replace wall panel near slide
                out and breaker box
CORRECTION:  . remove damage pall panel pull out all
                nails measurements taken cut new
                paneling to fit i also secured paneling
                and used batten strips for edges and
                putty the wall is now ok
WARR    COMPLAINT:  WARRANTY REPAIR 4 - The front forest   W    1021   FORES
                river decal is peeling
CAUSE:      The forest river decal is peeling, we
                will need to order a new forest river,
                FR logo and both swooshes
CORRECTION:  . REQUEST: .6 APPROVED: .6
WARR    COMPLAINT:  WARRANTY REPAIR 5 - the DS wheels are   W    1021   FORES
                missing valve stems
CAUSE:      Both DS tires were missing valve stem
                covers, i put new ones on.
CORRECTION:  Done. REQUEST: .1 APPROVED; .1
WARR    COMPLAINT:  WARRANTY REPAIR 6 - the shower handle   W    1021   FORES
                has a stress mark along the top
CAUSE:      The shower handle has a gray mark going
                along the top, i was very slightly able
                to scrape a small part of it with a
                blade and tried to scrub it with quik
                solv nither did enough to get rid of it
                so i took a black paint pen and covered
                it the best i could, the fauset still
                works
CORRECTION:  Done REQUEST: .3 APPROVED: .4
    
```

```

*****
Job # Part No      Description           PARTS   Bill to   Qty   Price   Total
*****
WARR0 013734116022 30# TANK                W-1021     1   144.98   144.98
WARR0 82208673     PANELING, LAUAN 5/32 X 4 W-1021     1    50.90    50.90
WARR0 822008736     MOLDING, BATTEN, 3.6MM X W-1021     3     2.34     7.02
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.02 140.00 2.80
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.34 140.00 47.60
ARR02 Z992 MISC LABOUR CODE (WARR EG W-1021 0.20 140.00 28.00
ARR03 Z992 MISC LABOUR CODE (WARR EG W-1021 0.00 140.00 0.00
ARR03 Z992 MISC LABOUR CODE (WARR EG W-1021 0.42 140.00 58.80
ARR03 Z992 MISC LABOUR CODE (WARR EG W-1021 1.03 140.00 144.20
ARR03 WARR MANUFACTURER WARRANTY JS W-1021 2.53 140.00 354.20
ARR04 Z992 MISC LABOUR CODE (WARR EG W-1021 0.60 140.00 84.00
    
```

Continued on page 3

Work Order : 12781B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR05 Z992      MISC LABOUR CODE (WARR EG  W-1021    0.10   140.00   14.00
ARR06 Z992      MISC LABOUR CODE (WARR EG  W-1021    0.40   140.00   56.00
*****
```

```
*****
Job #  Excode    Description  EXTRAS      bill to    Qty    Price    Total
*****
ARR01  SSE        SHOP SUPPLIES - EXTERNAL  W-1021    1.00    0.00    0.00
ARR03  FRT        FREIGHT      W-1021    1.00   46.80   46.80
ARR03  FRT        FREIGHT      W-1021    1.00  286.08  286.08
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021          202.90   789.60    0.00    332.88    0.00   1,325.38
*****
Totals          202.90   789.60    0.00    332.88    0.00   1,325.38
*****
```

&k2S
&k0S