

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12781B

Date In: 30 JAN 26 Author: MGRAY
Promised Date: 04 JUL 26 Stock No: 11469
: Year: 2026
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: PUMA CAMPING EDITION
: CHICAGO, IL Model: 305BHCE
Postal/Zip: 60673-1218 Miles/Hrs: 0
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: DB: 1/30
Purchased Date: 21 JUN 25 :
Delivery Date: 04 JUL 26 :
InService Date: :
Serial#: 5ZT2PUWB4T4026004 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - on the left bench of W 1021 FORES
the dinette table the wood support for
the seat on the wall is rotten
CAUSE: The support on the bench along the wall
was rotten and broken, i took the old
wood out and replaced it with a 1x2 from
the wood room
CORRECTION: Done REQUEST: .4
WARR COMPLAINT: WARRANTY REPAIR 2 - L.P tank is leaking W 1021 FORES
out the back
CAUSE: The back of the nozzle was leaking, i
replaced the tank with the same brand
from parts
CORRECTION: Done REQUEST: .6
WARR COMPLAINT: WARRANTY REPAIR 3 - wall on the ods next W 1021 FORES
to the cabinets across from the bathroom
had wall paper poorly stuck to it,
peeled it off and found a gouge in the
wall that they tried to cover from
factory
CAUSE: There is a gouge in the wall panel on
the ods by the cabinets across from the
bathroom we have a spare piece of wall
panel in the same color from the bunk
that i tried to use to cover it but the
panel is to short, we will have to order
a new panel, hight-78 Width-17 3/4 We
will also need baton strips in same

Continued on page 2

Work Order : 12781B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                color one broke in the process of taking
                                them off
CORRECTION:  REQUEST 3.0
WARR    COMPLAINT:  WARRANTY REPAIR 4 - The front forest   W    1021  FORES
                                river decal is peeling
CAUSE:    The forest river decal is peeling, we
                                will need to order a new forest river,
                                FR logo and both swooshes
CORRECTION:  . REQUEST: .6
WARR    COMPLAINT:  WARRANTY REPAIR 5 - the DS wheels are   W    1021  FORES
                                missing valve stems
CAUSE:    Both DS tires were missing valve stem
                                covers, i put new ones on.
CORRECTION:  Done. REQUEST: .1
WARR    COMPLAINT:  WARRANTY REPAIR 6 - the shower handle   W    1021  FORES
                                has a stress mark along the top
CAUSE:    The shower handle has a gray mark going
                                along the top, i was very slightly able
                                to scrape a small part of it with a
                                blade and tried to scrub it with quik
                                solv nither did enough to get rid of it
                                so i took a black paint pen and covered
                                it the best i could, the fauset still
                                works
CORRECTION:  Done REQUEST: .3
    
```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 013734116022 30# TANK                W-1021      1      144.98      144.98
    
```

```

*****
Job# Lab Code  Description  LABOUR  Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.16      140.00      22.40
ARR01 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.34      140.00      47.60
ARR02 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.50      140.00      70.00
ARR03 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.00      140.00      0.00
ARR03 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.42      140.00      58.80
ARR03 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.08      140.00      11.20
ARR04 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.50      140.00      70.00
ARR05 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.50      140.00      70.00
ARR06 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.50      140.00      70.00
    
```

```

*****
Job # Excode      Description  EXTRAS      bill to      Qty      Price      Total
*****
ARR01 SSE          SHOP SUPPLIES - EXTERNAL  W-1021      1.00      0.00      0.00
    
```

Continued on page 3

Work Order : 12781B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	144.98	420.00	0.00	0.00	0.00	564.98
	Totals	144.98	420.00	0.00	0.00	0.00	564.98

&k2S
&k0S