

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12911B

Date In:	01 APR 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	11422
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	PUMA DESTINATION
:	WISCONSIN RAPIDS, WI	Model:	429LFT
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 4/4
Purchased Date:	21 MAR 26	:	:
Delivery Date:	04 JUL 26	:	:
InService Date:	:	:	:
Serial#:	4X4TPU822TP106946	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - rear bathroom            W    1021    FORES
          sliding door came off the guide
          CAUSE:        The rear bathroom sliding door fell off
                       the guide, i was able to put it back ok
                       and it works now
          CORRECTION:  Done  requesst: .2
WARR    COMPLAINT:  WARRANTY REPAIR 2 -cabinet door in the        W    1021    FORES
          rear bunk room wont latch properly on
          the bottom latch.
          CAUSE:        The bottom latch on the cabinet door in
                       the rear bedroom wouldnt latch on the
                       bottom, i went to move the bracket down
                       and the corner is cracked, the door also
                       looks slightly warped the top is hitting
                       before the bottom, we will need to order
                       a new door The door measures 14Wx32L
          CORRECTION:  ..  request: .5
WARR    COMPLAINT:  WARRANTY REPAIR 3 - the kitchen fauset        W    1021    FORES
          is not working.
          CAUSE:        The kitchen fauset is not working, the
                       spray head on the main fauset is either
                       clogged or broken inside sink works
                       without it and all other fauset work,
                       we will either need a whole new fauset
                       or just the head.
          CORRECTION:  request: .6
WARR    COMPLAINT:  WARRANTY REPAIR 4 -one of the latches        W    1021    FORES
          for the water heater door is missing
```

Continued on page 2

Work Order : 12911B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      CAUSE:       The cam lock fastener on the water
                   heater door was missing, the ones we
                   have are to short we will have to order
                   a set from manufacture
      CORRECTION:  .. request: .6

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 014717092135 CAM LOCK WATER HEATER ST W-1021      1      6.31      6.31

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.50      140.00      70.00
ARR02 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.43      140.00      60.20
ARR02 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.07      140.00      9.80
ARR02 RV32A-2   CABINET DOOR R&R RVDA      W-1021      0.00      140.00      0.00
ARR03 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.50      140.00      70.00
ARR04 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.05      140.00      7.00
ARR04 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.45      140.00      63.00

```

```

*****
Job #  Excode      Description  EXTRAS      bill to      Qty      Price      Total
*****
ARR01  SSE          SHOP SUPPLIES - EXTERNAL  W-1021      1.00      0.00      0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021          6.31      280.00      0.00      0.00      0.00      286.31

      Totals          6.31      280.00      0.00      0.00      0.00      286.31

```

&k2S
&k0S