

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13211B

Date In:	13 MAR 26	Author:	MGRAY
Promised Date:	06 APR 26	Stock No:	11475
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	403LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DEL@ST- 4/6@9 - DB:3/1
Purchased Date:	06 FEB 26	:	:
Delivery Date:	04 JUL 26	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS27TP107017	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 2 - DS FRONT SEAL ON      W    1021    FORES
        CAUSE:      Bulb seal came loose
        CORRECTION:  Removed screw at bottom holding bulb
                    seal on, removed the seal sprayed track
                    with silicone then put seal back on put
                    screw in bottom and added one at top to
                    hold seal in place  REQUEST:.2
WARR    COMPLAINT:  WARRANTY REPAIR 3 - windows have smeared W    1021    FORES
        CAUSE:      Smeared silicone on all windows
        CORRECTION:  Used quick solve to clean away the
                    silicone  REQUEST: .5
WARR    COMPLAINT:  WARRANTY REPAIR 4 - Ods pull out bed one W    1021    FORES
        CAUSE:      Missing bolt
        CORRECTION:  I loosened other bolts and tapped the
                    back over now the missing bolts hole is
                    visible installed a bolt and nut
                    tightened then tightened the other 3
                    bolts  REQUEST:.3
WARR    COMPLAINT:  WARRANTY REPAIR 5 - Finish on grey      W    1021    FORES
        CAUSE:      The grey strainer with kitchen sink has
                    bubbling in the finish happening
                    PLEASE ORDER NEW GREY STRAINER PICS
                    TAKEN
        CORRECTION:  .....  REQUEST: .2
```

Continued on page 2

Work Order : 13211B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 6 - Carpet on the steps E    17974  LONTO
          to the loft has loose strings and is cut
          too short on the one side can see bare
          wood
          CAUSE:      Carpeting cut too short and loose
                      strings all over steps
          CORRECTION: VACUMJED STEPS REMOVED STRINGS THEN USED
                      A SMALL PICK TO PUCK EDGE OF CARPET TO
                      FLUFF UP AND HIDE THE BARE EDGES PLEASE
                      ADJUST MY TIME REQUEST: .2
WARR    COMPLAINT:  WARRANTY REPAIR 7 -THE BENCH SEAT AT W    1021  FORES
          DINING TABLE HAS A STAIN IN TOP CENTER
          OF CUSHION
          CAUSE:      Slight stain on bench seat
          CORRECTION: Used fabric cleaner to remove the stain
                      REQUEST: .1
WARR    COMPLAINT:  WARRANTY REPAIR 8 - 4 slide rooms need W    1021  FORES
          to get redone so water will not enter
          unit and create rot
          CAUSE:      Mfg did not assemble correctly
          CORRECTION: Request 8 hours to remove fascia on the
                      4 slides remove nails from fascia repair
                      bare wood area by adding waterproof
                      material so water cannot reach wood and
                      rot then reinstall all fascia on all 4
                      sliderooms REQUEST: 8.0HR
WARR    COMPLAINT:  WARRANTY REPAIR 11 - KITCHENS HEAT VENT W    1021  FORES
          IN FLOOR IS CRACKED
          CAUSE:      Over torqued at mfg ORDERED NEW BY ANNA
                      ON 3/12 TAN FLOOR REGISTER
          CORRECTION: ..... REQUEST: .2

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.34  140.00  47.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.01  140.00   1.40
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.15  140.00  21.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.20  140.00  28.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.30  140.00  42.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.00  140.00   0.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.00  140.00   0.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD E-17974  0.50  130.00  65.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.45  140.00  63.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.05  140.00   7.00
ARR11 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00

```

Continued on page 3

Work Order : 13211B

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR02  SSE      SHOP SUPPLIES - EXTERNAL  W-1021    1.00    4.88     4.88
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
E    17974        0.00     65.00     0.00     0.00     3.58     68.58
W    1021         0.00    490.00     0.00     4.88     0.00    494.88

      Totals        0.00    555.00     0.00     4.88     3.58    563.46

```

&k2S
&k0S